Form B03

Scheduled Maintenance Work Order



Quantum Medical Solutions sdn blid transcending boundaries, transforming life

Format Ref. - QMS/TSD-003 Rev. 00

			1000	21 2.16
Work Order No	pw0372187	Scheduled Month	FEBURI	27 2018
Work Order Date	112/18 mutiARA	Completed Date	12/2/28/8	
Clinic Name	FUNK I MALAYSHI (TIM MEROPA)	Clinic Code	Wholb	
BE No	wflood lbq	District	W. Lab	van.
BE Category	SCALES JUFAMT	WO Assigned to	tot Note	, Astmas
Ownership	Existing Equipment	☐ New & Purchased Eq	juipment "	
BE Condition	☐ Under Warranty	☐ BER Proposed		
	☐ Preventive Maintenance (PM)	☐ Third Party Calibratio	n (TPC)	
Work Order Type	Routine Inspection (RI)	Statutory Certification	(SC)	
BE Third Party Ca	l dibration / Statutory Certification Details	ir lacini debi (5)		
Company Name		Cal / Cert Date	٨,	
Contact Number	NA /	Cal / Cert Expiry Date	/ / / /	
Schedule Mainten	ance Execution Details			a zasa anasan
SI No	QMS Engineer / Technician Name	Date	Start Time	End Time
	enen. Desenta 8 populerorali Biomedicae tessectar, gas 819-3804814	12/2/2018	12-00pm	12-30pm
L Customer Remarks				
Engineer / Technici	an Signature	Customer Signature		
Name	A 100 (100 (100 (100 (100 (100 (100 (100	Name	M	
Date	Minno Asumare o mono horam Biomedical Vertencian, gens	Designation	[
	010-2036231	Date	IAIZZA MAIDIN	
1	(/ 2)		g Pegawai Perubat	an U29
For Internal Use on	2/2/2018			

First Verification

QMS Circle Incharge

Juuns Jansun Biomedical Engineer, QMG 019-3620179

Final Verification

QMS State Incharge

SABAH STATE MANAGER QUANTUM MEDICAL SOLUTIONS SON BHD



Quantum Medical Solutions Sdn Bhd

BEMS Planned Preventive Maintenance Checklist

Scales,Infant BE CODE: 13-462

CHECKLIST NO: CL-131 REV,000

		j j					DE O	OUL.	13-702						
PAF	RT1 ASSET DE	TAILS													
WOF	RK ORDER NO	· pu	1037	118	37	-					ASSET NO	>	WPL 00	0169	•
MAN	UFACTURER	► N	11		1						MODEL	•	h (14		
FRE	QUENCY	► 3 MONT	HLY ()	6 MO	NTHL	.Y ()		12 MONTHLY	1	PPM HOURS	•	0-5		
PAF	RT 2 SPECIAL F	RECAUTION	444	i di ka						64499					
If the	re is evidence of	body fluid contai	mination, s	submit the	e devi	ce for	cleaning	and	decontamination	on before ins	specting it.				
Wea	r appropriate Per	sonnel Protectio	n Equipme	ent (PPE)	durin	ig wor	k.								
	r grounded electr			_				-							
	r to the safety pro				nd gul	ldance	e as per i	manu	facturer guideli	nes.					
	e sure the test eq		e duly call	orateo.											
٠.	(√) where approp														
		SET NO			DI	ESCR	IPTION			5	SERIAL NO		CALIBRA	TION '	DUE ON
	<u> </u>	1 }	ELECTR	ICAL SA	FETY	ANAI	LYZER				NA			NA	
		, , , , , , , , , , , , , , , , , , ,	WEIGHT	·s						cc 26	17-64	<u></u>	24,	17	18
										- 12	. •••				<u> </u>
PAR	RT 4 QUALITAT	IVE TASKS													
	(√) where approp														
	(,)e. approp			PASS	F	AIL	NA						PASS	FAIL	NA
				_											
1	Chassis - verify poleanliness and of			(/)	()	()	8	Controls/Swite controls	ches - verify	proper operation	of	(/) ()	()
2	Mount/ Fasteners	s - verify physica	I integrity	()	()	(/)	9	Indicators/ Dis	splays - verif	y proper illuminati	ion	(/) ()	()
							/		•						•
3	Cables - verify in	tegrity		()	()	(/)	10	Infant tray -Ve	rify physical	integrity		(() ()	()
4	AC Plug - verify i	ntegrity		()	()	(/)	11	Calibration				() ()	
						-									7
5	Power Cord - ver integrity	rify proper insula	tion and	()	()	(/)								
6	Strain Relief - ve	erify physical inte	grity at	()	()	(/)								
	both ends of line	cord					-								
7	Fittings/Connector			(/)	()	()								
PAF	RT 5 PREVENTI	VE MAINTENAI	ICE TASK	(S											
Tick (($$) where approp	riate				300.000									-
				DONE	DC	OT ONE	NA	Note	es:						
1	Clean the Exterio	or/Interior				**)	()				is defined as NO			Ω	
											d 'NOT DONE', the er Applicable	.⇔. I]	uəlliy III Fall	,	
2	Adjust/align mec	hanical compone	ents	(/)) ()	()								
3	Clean Infant tray			(/)) ()	()								

Quantum Medical Solutions Sdn Bhd

BEMS Planned Preventive Maintenance Checklist Scales, Infant BE CODE: 13-462

CHECKLIST NO: CL-131 REV.000

0						Units /	Set	Measured			5400	CAIL	NI A	
·			scription			UOM	Values	Values	<u> </u>	olerance	PASS	FAIL	NA	
٧	Veight M	sing 5	req)			gers	AN	5	4	(00/,	<u> </u>	())
		Ą	'J'			ig				t	()	()	()
											()	()	()
								<u> </u>						
									-					

Т7	LECTRICAL	SAFETY TES	T					The state of the s		1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			71 77 10 7 77 77 77 77 77 77 77 77 77 77 77 77
TRIC	AL SAFETY T	EST, (attach	report)											
(n accordance to IE		г			┌ .								
	L	PASS		FA	IL		NA							
тя	IOTES													
ART 8	OTES								A service of the serv					
													ΓΑ	
													ſ.	
											HAIZ	ZA M		IN
			OTIVE MAIN	UTEMANO			[7]	FINCTION	NING		HAIZ nolong Pe	ZA M gawai gawai	All	IN Datan L
		CORRE	CTIVE MAIN	VTENANC	E REQUIF	RED	Z	FUNCTION	NING		nolong Pe NOT FUNCTION	gawai DNING	Aid	IN Datan L
Wol	RK ORDER NO		CTIVE MAIN	√TENANC Λ		RED		FUNCTION	NING		HAIZ nolong Po NOT FUNCTK NEXT PPM DA	gawai DNING		IN patanし
wor	RK ORDER NO		CTIVE MAIN			RED		FUNCTION	NING		nolong Pe NOT FUNCTION	gawai DNING		IN patan L
) ▶		<u> </u>	A	· · · · · ·	ioning to ti				nolong Pe NOT FUNCTION	gawai DNING	A L	IN patan L
PM has	been performe) ▶	nce to the ch	necklist and	A d the equip	· · · · · ·	ioning to th				nolong Pe NOT FUNCTION	gawai DNING		IN patan L