Form B03

Scheduled Maintenance Work Order





Quantum Medical Solutions son bhd transcending boundaries, transforming life

Format Ref: - QMS/TSD-022 Rev.01

				Control of the Contro				
Work Order No.	PWO365278	Schedu	le Month	June 2018				
Work Order Date	01/06/2018	Comple	ted Date	24/6/10	<i>~</i>			
Clinic Name	Klinik Pergigian Selkolah Menengah Le	Clinic C	ode	JHR556				
BE No.	JHR023432	Distict		LEDANG				
BE Category	STERILIZING UNITS, PORTABLE	WO Ass	igned to	Rebeah -				
Ownership	✓ Existing Equipment		Purchase	New				
BE Condition	✓ Active		BER Proposed					
W 1 0 1 - T	✓ Preventive Maintenance (PM)		Third Party Calibra	tion (TPC)				
Work Order Type	Routine Inspection (RI)		Statutory Certificati	on (SC)				
Reschedule Date								
BE Third Party Calibra	ation / Statutory Certification Details				10			
Company Name	n/5	Cal / Ce	ert Date	~	Un			
Contact Number	w/B	Cal / Ce	ert Expiry Date	٨	P			
Action Taken								
Corrective N	done as per checklist. Unit tested functioning go Maintenance / Breakdown Availability: Yes / NA Ppm done as perchecklist			Manufacturer: 分 Modal: 分句 Serial No: 110				
Schedule Maintenanc	e Execution Details							
SI No	QMS Engineer / Technician Name		Date	Start Time	End Time			
1	pebech		25/6/18	19-07	12.00			
Customer Remarks								
Quar	ignature R RABEAN BINTI AZN, E titum Medica Sutton Sdn. 8 echnical Service Departmen Tel: 012-3968095	Custome Name Designa Date Seal	PEGAWA	SARINA ALI PERGIGIAN C 3928				
For Internal Use								

First Verification

QMS Circle Incharge

Biomedical Engineering
Cashorn Medical Solutions
HyP: 012-3967638

Final Verification QMS State Incharge

KEMENTERIAN KESIHATAN MALAYSIA

MEET Planned Preventive Maintenance Checklist

CHECKLIST NO:CL-147-000 REV.001

1									s, Portable DE-031					NL V.00			
PART 1	ASSET DETAILS			4.5					5666B								
WORK O	RDER NO ► X	w03	6524	16							ASSET NO	· 7	4 12	- 60	3 0	037	
MANUFAC		Skall									MODEL	· ()	lati,	n 1	00	٥Ē	
FREQUEN	NCY ►	, ,	HLY () 61	иоитн	LY (/)		12 MONTHLY	()	PPM HOURS						
	SPECIAL PRECAU		211100			•											
	evidence of body flu		nination, s	ubmit the	device f	for clea	ning	and	decontaminatio	n before in:	specting it.						
Wear appi	ropriate Personnel I	Protection	ı Equipme	ent (PPE) o	luring w	ork.											
Wear grou	unded electrostatic	wristband	when har	ndling PCB	or elec	tronic c	omp	oner	nts.								
Refer to th	ne safety procedure	for addition	onal preca	utions and	d guidar	nce as p	er n	nanu	facturer guidelir	ies.							
Make sure	the test equipment	t used are	duly calib	orated.													
PART 3	TEST APPARATU	S															
Tick (√) w	vhere appropriate		1011,000,000,000,000,000					220 1100 01201			20041,00040,00040						
NO	ASSET NO)			DESC	CRIPTIO	NC			;	SERIAL NO	C	ALIBR	OITAS	1 DUE	ON	
4	TEESAOL	78	DIGITAL	TEMPERA	ATURE	PROB	E			324	6911						
)	TEESA 03.	38	DIGITAL	PRESSU	RE MET	ER				#31	3545 h	-8	111	118			
											3 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2						
PART 4	QUALITATIVE TA	SKS															
	where appropriate																
, ,	**			PASS	FAIL	N	4					PA	SS	FAIL		NA	
	ssis - verify physical			(/)	() ()	9	Over pressure integrity	cut of valve	e - Verify physical	5	1)	() ()	
									Door lock - Ve	zan	15-1	,	1	,			
1	er Cord - verify prop ntegrity	er insulati	ion		() ()	10	Door lock - Ve	rity pnysica	i integrity	(-/)	() ()	
3 Strair	n Relief - verify phys	sical integ	ırity	()	() ()	11	Door gasket V	erify physic	cal integrity	(/	1)	() ()	
at bo	th ends of line cord									,	,						
	gs/ Connectors - ch	neck all		1/5	() ()	12	Check water to	ınk leak		(/	/)	() ()	
	Strey	•	i										/.				
	ros/Switches - verit ation of controls	fy proper		(/)	() ()	13	Check drain va	ilve -Physic	cal integrity)	() ()	
6 Indic	ators/ Displays ve	rify proper	ſ	(/)	() ()	14	Check label			(-	7)	() (
	ination and operation			,	N 12	, (11.20	:50 :		20 20		
7 Chec	ck fuse, circuit break	ker		(/)	() ()	15		Resevoir/Bo	ottle - clean & verify	(-	<u>—</u>)	() ()	
8 Heat	er - verify physical I	ntegrity		(/)	. () ()		integrity								
l 9 Char	mber/cassette- ver	ify physica	al														
	rity (scalling, rusting			(/)													
PART 5	PREVENTIVE MAI	INTENAN	CE TASK	(S													
$Tick(\sqrt{y})$ w	where appropriate																
				DONE	NOT DONE	. N	A					DC	NE	DONE		NA	
1 Clear	n exterior and interi	or of the		(/	() ()	4	Lubricate all m	oving parts	S	() (**)(_		
equip	oment			-	_										1		
2 Chec	ck/replace gasket	***			() ()	Note	es:								
3 Chec	ck/ clean solenoids			()	()(/	/)				is defined as NOT						
											d 'NOT DONE', then ver Applicable	n justify	in Parl	8 1			



KEMENTERIAN KESIHATAN MALAYSIA

MEET Planned Preventive Maintenance Checklist

Sterlizing units, Portable

BE CODE: DE-031

CHECKLIST NO:CL-147-000 REV.001

WORK Order No

No	Description	Checked	Serv	/ice/ ean	Repl	aced	Not Applicable	No	Description	Chec	ked	Servi	ce/CI an	Replac	ed	Not Applicat
1	Fuses	(1)	()	()	()	16	Chamber Guard Seal (if applicable)	()	()	()	
2	Main Control Board	(/)	()	()	()	17	Solid State Relay (if applicable)	()	()	()	(/)
3	Fan Running Rear & Side (if applicable)	()	()	()	/	18	Thermostat Assembly	()	()	()	(Z)
4	Clean Water Resevoir	(/)	()	()	()	19	Thermal Printer (if applicable)	()	()	()	(/)
5	Electric Door Lock	()	()	()	(/)	20	Vacuum Pump (if applicable)	()	()	()	(\mathcal{I})
6	Pressure Door Lock	()	()	()	(/)	21	Temperature Sensor	()	1	()	()	()
7	Discharge Door Lock	()	()	()	()	22	Filters	("	1	()	()	()
В	Pressure Transducer	(/)	()	()	()									
9	Pressure Gauge	(/)	()	()	()									
0	Safety Valve	()	()	()	(/)									
1	Air Valve/Steam Solenoid Valve (if applicable)	<u>(</u> /)	()	()	()									
2	Discharge Valve	()	()	()	(/)									
3	Feed Water Valve (if applicable)		()	()	()									
14	Heating Element	(/)	()	()	()									
15	Door Gasket/Cessette Seal	(/	()	()	()									
Α	Technician Remarks															
									20							
							N	A	/							
					/											
				,	/											



KEMENTERIAN KESIHATAN MALAYSIA

MEET Planned Preventive Maintenance Checklist Sterlizing units, Portable BE CODE : DE-031 CHECKLIST NO:CL-147-000 REV.001

WORK ORDER NO - PW0365218

PART 8	QUANTITATIVE TASKS								
Fick (√)	where appropriate	Units /	Set	Measured					
No	Description	UOM	Values	Values	Limit/Tolerance	PASS	FAIL	NA	
1	Temperature reading	°C	134°C	13600	134-137 121-124	(/)	()	(ì
2	Pressure reading - non absolute pressure reading	bar	2.15	2-10	2.03-2.32 1.04-1.24	1	()	()
3	Electrical Supply Voltage	V	2400	refer to EST	Refer to Nameplate	1	()	(ĺ
4	Electrical Power/Consumption	kW		refer to EST	Refer to Nameplate	/	()	().
	ELECTRICAL SAFETY TEST								
ELECTR	CAL SAFETY TEST, (attach report)								
	(In accordance to IEC 60601)								
	PASS FAIL		AV						
PART 10	NOTES								
Self-Sentition									
				J.					
			4						
		. 1	VA						
									•
	CORRECTIVE MAINTENANCE REQUIRED			FUNCTION	ING	NOT FUNCTION	IING		
	CORRECTIVE MAINTENANCE REQUIRED			, GIAG HOIN				0.	
WO	RK ORDER NO ▶	/				NEXT PPM DAT	E ► _	n	19
DDM 1	been performed in accordance to the checklist and the equipmen	t is function	ning to th	e intended nu	rnose				
		i is iunicae	ning to th	о ппениви ри	WITNESSED BY:				
COMPLE	ETED BY:				WITHESSED BY:				
	7								
DATE:	`)				DATE:				

Date: 25/6/2018

Test Setup

DUT Information

Operator ID:

Calibration Tech:

NADIA

Calibration Date:

25/8/2018

Firmware Version :

Serial Number:

2.08.01

Date & Time:

3246911

25/06/2018 & 11:00 P.M

JOB Name:

Equipment Number: JHR 023432

Serial Number:

110311F00003

Manufacturer:

SCICAN

Model:

STATIM 2000E

Location:

KP SEKOLAH SIALANG

Other:

Template Information

Template Name:

62353-Alt.STERILIZING

Standard:

IEC62353-Direct

Pause after Power ON: NO

Power ON delay:

2

Power OFF delay:

Test Mode:

0

Test Speed: **NORMAL** Halt on Test Failure: YES

Multi PE Test:

AUTO NO

Include Time:

YES

Multi Resstore:

WORST/LAST

Insulation Resistance \ 500V

Multi Enclosure Test: NO

Reverse Polarity:

Pause before Power O NO

YES

Classification:

Ï

PLC Configuration-Applied part setup

AP Name AP Type

AP Num

ESA615 Test Results

Test Name	Value	High Limits Low Limits	Status
Protective Earth Resistance	0.003 Ohr	- 0.3 -	P
Insulation Resistance			P
Mains to Protective Earth	72.2 MOh	ıı	Р
Mains Voltage			Р
Live to Neutral	237.3 V		Р
Neutral to Earth	2.63V		Р
Live to Earth	239.7 V		P
Equipment Current	0.4 A		P
Direct Equipment Leakage			Р
Open Earth	34.7 uA	500 -	Р
Open Earth- Reversed Mains	56.9 uA	500 -	Р
BERNINE MARKERS - MARKERSHAMMER MARKERSHAMMER - MARKAMAR MARKERSHAMMER MARKERSHAM - BASKAMAR MARKERSHAMMER MARKERSHAMME			

