## Form B03

## **Scheduled Maintenance Work Order**



Format Ref:- QMS/TSD-022 Rev.01

		a wayin see						
Work Order No	~/0 PW0407717	Sch	eduled Month	January 2019				
Work Order Date	No 1/01/2019	Con	pleted Date	11/1/20	19			
Clinic Name	K K PERGKACAN HUCH	Clini	c Code	PRKOIH				
BE No	PRK030248	Dist	rict	HULL DE	ROK			
BE Category	HEMBTOLEGY PROCYDERIA	wo	Assigned to	reer DJ.				
Ownership	Existing Equipment		MEET Equipment					
BE Condition	Under Warranty		BER Proposed					
Work Order Type	Preventive Maintenance (PM)							
Work Order Type	Routine Inspection (RI)		Statutory Certification	n (SC)				
Reschedule Date								
BE Third Party Ca	libration / Statutory Certification Details							
Company Name	N/D	Cal /	Cert Date	n	n			
Contact Number	N/P	Cal /	Cert Expiry Date	No				
* REPZACE PNO RBC EDUCTY	to THE NEW WRC CHOI VIRIAG CORD DUK	NBC TO	S/N : .B. Purchase Kewpa No	D-4	W BKB KK   1612			
Schedule Maintena	nce Execution Details							
SI No	QMS Engineer / Technician Name		, Date	Start Time	End Time			
1 080	oul		11/1/2019	15:00	18:50			
Date / / / Defition No 10 Greentow	DR AZARUL B AHAMAD BRAK LAB SPECIALIST Medical Solution Sdn. Bhd B, Persiaan Greentown 4c MA Avenue, 30450 Ipoh, Peral 1-2461991 Hp: 012-39648013	Customer Signature  Name  Designation  Date  MOHD EZHAN BIN SANUSI  Juruteknologi Makmal Perubatan U29  Klinik Kesihatan Pengkalan Hudu  33100 Pengkalan Hudu, Perak						
For Internal Use only	,							

First Verification QMS Circle Incharge Final Verification QMS State Incharge



## KEMENTERIAN KESIHATAN MALAYSIA

MEET Planned Preventive Maintenance Checklist Analyzers, Laboratory, Hematology, Cell Counting, Automed ( Medium)

CHECKLIST NO:CL-015-000 REV.000

			BE C	ODE : ME-009					
PART 1 ASS	SET DETAILS								
WORK ORDE	ER NO . MA	PW04077	14		BE NO			48	
MANUFACTU	RER - SUSM	BX			MODEL	· XPI	· xPico		
FREQUENCY	► 6 MONTH	LY (/ ) 12 M	ONTHLY (	)	PPM HOURS	▶ 2.00			
PART 2 SPE	CIAL PRECAUTION						rdig adempirer Significações participa		
Wear appropriate Wear grounded Refer to the sale Make sure the	ate Personnel Protection  d electrostatic wristband w  fety procedure for addition  test equipment used are	Equipment (PPE) during when handling PCB or an anal precautions and gu	ng work. electronic com	ponents.	,				
Tick ( v ) where	appropriate				·				
NO ASSET NO		DESCRIPTION			SERIAL NO	CALIB	CALIBRATION DUE ON		
	/n- E	ELECTRICAL SAFETY	ANALYZER		<u> </u>	~10 -	_		
	ASSET DETAILS  RK ORDER NO								
	mente una la sura casa de la califacta caraca en caraca en caraca casa casa en casa en casa en casa en casa en	(/)(	) ( )	11 Probes- Verify	physical interigity	(J)	( ) (	)	
		itegrity ( / ) (	) ( )	12 Temperature	system- verify proper operation	( / )	( )(	)	
integrity 4 Strain Reli	ief - verify physical integri	,		integrity and p	roper operation				
		(/)(	) ( )	15 Printer - Verify	physical operation.	( , )	( ) (	)	
Control of the same of the sam		eration ( / ) (	) ( )	16 User Setting -	Verify Operation	/		)	
of controls 7 Indicators/0	Displays- verify proper op		) ( )	17 User calibration	n - Verify Operation	,		)	
					c - Verify Operation			)	
integrity	20 100 CA			WAS 1	III			,	
physical int	egrity			10 Tidle Hieroria	The danishation - volley operation	,	, , ,	, ,	
	and a surface of the	Zarraz argum manasanas ay arg							
				Mark Comment of Comment of Comment		DISTRIBUTE OF STREET	Last Control of Seath Control		
			SSS (SSS)			DONE		NA	
	rior and interior of the	(/)(	) ( )	6 Clean measuri	ng area	(/)	( )(	)	
20 AP 100 CONTRACTOR	an interior of unit	(/)(	) ( )	7 Calibrate syste	em parameter	(/)	( )(	)	
3 Clean hydra	aulics and pneumatic sys	tem ( / ) (	) ( )	8 Perform Post	outine	(/)	( )(	)	
4 Tubings - cl	lean/ replace ***	(/)(	) (	Notes:					
5 Clean samp	oling mechanism	(/)(	) ( )	** If you	have ticked 'NOT DONE', ther				

## KEMENTERIAN KESIHATAN MALAYSIA



<u> </u>					£108±9	110:015-300	766T9+7-50	: xej/191		
					7tc	January 1904,			11/11	: 31
					bha.	SPECIALIST	PERAK LAB	Juant	/	
						DANAHA 8 JI	JAASA AOO		Y8 QЭT	
		- <del>0</del> :	sodind bebnetni	ett of Eni	noitanut si tr	emqiupe edi bas is	ce to the checkli	——————————————————————————————————————	moheq need	SEA N
-P 100 00	■ 3TAO M99	NEXT			-	Ø		o	К ОВDEВ И	ROW
Inm I								711100 F	_	
	NUCTIONING	3 TON	FUNCTIONING	$\mathcal{L}$	7	HANCE REQUIRED	ARTINEM AVITE	38803		
73081	near	HOS V	2000	1 6	NI	INNO	11/1	nos	32	CO
1821		1000 000	1011	2 20	1 3/	AJ 700	100 1	10000	10	/ IX
1591	りしょう	05 74	18 OLC	13)	d a	07 000		000	50 8	n
									NOTES	₿ TЯA
	AV	FAIL	SSA9	Result:	5353	1010 IEC 63	01    IEC 9	IEC	su bhabhafa	
				. # 11000					uddn элэцм	( \ ) y:
				nii valtana med				Y TEST, (attact		
							18	AL SAFETY TE	ELECTRIC	∇ TЯA
	- V -								11 E II 11	
12										
					,					
25 2		- AHWH.	20110	00	410	_		78-37	22	7
		- Myuf	400110	25	1111-	HECK -	over.	EBRO	300	.)
AN	PASS FAIL	-imit/Tolerance	Measured sellev	Set Values	\ atinU MOU		Description			οN
								અપ્રવાહ	douddo ənəyn (	בוך א
						1,111,0	h om t	VIIVE TASKS		
					: 7000 70	£164.9	11 Arid	1	OKDEK NO	NORK
		(muibeM)		nuoD lleD		ers, Laboratory, He	zylenA	1000	Contract of the same	·
O:CF-012-000 KEA:000	CHECKLIST NO	3.00				MEET Planner			Vinda /	7

