# Conveyor_SOP_v3 - Scope & Safety

Document: Conveyor_SOP_v3.pdf  Revision: A  Section: Belt Misalignment

Scope: maintenance procedure for belt misalignment on plant equipment.

PPE: ISI helmet, cut-resistant gloves, safety goggles. Isolate power and apply lockout/tagout (LOTO). Operator fatigue below 70%. Written supervisor approval is required before starting.

# Belt Misalignment - Procedure

Follow these steps in order:

1. Stop conveyor + LOTO
2. Inspect idlers
3. Adjust take-up evenly
4. Re-tension to spec
5. Run empty 5min

# Belt Misalignment - Symptoms, Limits & Escalation

Symptoms and limits: Belt drifting >10mm off centre.

Keywords: conveyor, belt, misalign, drift

Escalate to the maintenance supervisor if the fault persists after one attempt.