Quality_SOP_v4 - Scope & Safety

Document: Quality_SOP_v4.pdf Revision: A Section: Surface Defect

Scope: maintenance procedure for surface defect on plant equipment.

PPE: ISI helmet, cut-resistant gloves, safety goggles. Isolate power and apply lockout/tagout (LOTO). Operator fatigue below 70%. Written supervisor approval is required before starting.

Surface Defect - Procedure

Follow these steps in order:

1. Stop conveyor
2. Photo defect
3. Check mold pressure 150bar
4. Check temp 180C
5. Re-calibrate

Surface Defect - Symptoms, Limits & Escalation

Symptoms and limits: Scratch defect <0.2mm acceptable.

Keywords: defect, scratch, quality, dent, surface

Escalate to the maintenance supervisor if the fault persists after one attempt.