Safety_SOP_v1 - Scope & Safety

Document: Safety_SOP_v1.pdf Revision: A Section: Safety Checklist

Scope: maintenance procedure for safety checklist on plant equipment.

PPE: ISI helmet, cut-resistant gloves, safety goggles. Isolate power and apply lockout/tagout (LOTO). Operator fatigue below 70%. Written supervisor approval is required before starting.

Safety Checklist - Procedure

Safety before maintenance: Helmet ISI, Gloves cut-resistant, Goggles, Power isolated, Fatigue <70%, Supervisor approval

Safety Checklist - Symptoms, Limits & Escalation

Symptoms and limits: Safety before maintenance: Helmet ISI, Gloves cut-resistant, Goggles, Power isolated, Fatigue <70%, Supervisor approval

Keywords: safety, helmet, ppe, gloves, loto, maintenance checklist

Escalate to the maintenance supervisor if the fault persists after one attempt.