



TO: David Helbock
1525 Wilson Blvd, Suite 225
Arlington, VA 22209

FROM: Matt Arnold, on behalf of the FICAM Testing Program

DATE: 02/11/2025

RE: **Updated Approval Letter for Listing on the GSA APL**

The Office of Management and Budget (OMB) issued M-19-17, which requires federal agencies to procure only qualified products and services listed on the GSA Approved Products List (APL) when implementing HSPD-12 in their environment. Procuring approved products and services facilitates the government-wide objective of a federated and interoperable ICAM segment architecture. It also ensures compliance, consistency, and alignment of commercially available products and services with the requirements and functional needs of government ICAM implementers.

Accordingly, the FIPS 201 Evaluation Program (Program) is very pleased to inform you that the following product/service has passed testing against all applicable Testing Requirements. Please see the attached document that summarizes the specific parameters of the approval (e.g., product/service profile and what your product/service was tested with). Your product/service will now be listed on the APL, as shown below. If there are any errors in the listing information, please notify me within five (5) business days of receiving this letter.

1 Category-PACS and Validation Infrastructure

1.1 APL Certification Number

- (APL# 10103)
 - Velocity Security Management System
 - Velocity Certificate Service
 - Hirsch MX-8 Panel
 - Hirsch MX-4 Panel
 - Hirsch MX-2 Panel
 - Secure Network Interface Board v3 (SNIB3)
 - RS-485 Reader Expansion Board (RREB)
 - Hirsch MX1 Panel
 - Hirsch MX1 ME Panel

1.2 Product/Service Information

Organization Name:	Identiv
Name of Product or Service:	Velocity Security Management System
Part Number:	VELFED100
Hardware Version:	N/A
Software Version:	3.8.6
Firmware Version:	N/A

Organization Name:	Identiv
Name of Product or Service:	Velocity Certificate Check Service
Part Number:	VEL-VCCS
Hardware Version:	N/A
Software Version:	3.8.6
Firmware Version:	N/A

Organization Name:	Identiv
Name of Product or Service:	Mx-8 - Hirsch MX controller series with SNIB3 and RREB
Part Number:	Mx-8-S3OB
Hardware Version:	7
Software Version:	N/A
Firmware Version:	CCM/CCMx 8.3.00.73/ SNIB3 4.02.1554
Is an Exemplar:	Yes
APL:	10103

Organization Name:	Identiv
Name of Product or Service:	Mx-8 - Hirsch MX controller series with SNIB3 and RREB
Part Number:	Mx-8-N3-FICAM
Hardware Version:	7
Software Version:	N/A
Firmware Version:	CCM/CCMx 8.3.00.73 / SNIB3 4.02.1554

Has an Exemplar:	Yes, Part Number Mx-8-S3OB (APL #10103)
APL:	10103

Organization Name:	Identiv
Name of Product or Service:	Mx-4 - Hirsch MX controller series with SNIB3 and RREB
Part Number:	Mx-4-S3OB
Hardware Version:	7
Software Version:	N/A
Firmware Version:	CCM/CCMx 8.3.00.73/ SNIB3 4.02.1554
Has an Exemplar:	Yes, Part Number Mx-8-S3OB (APL #10103)
APL:	10103

Organization Name:	Identiv
Name of Product or Service:	Mx-4 - Hirsch MX controller series with SNIB3 and RREB
Part Number:	Mx-4-N3-FICAM
Hardware Version:	7
Software Version:	N/A
Firmware Version:	CCM/CCMx 8.3.00.73/ SNIB3 4.02.1554
Has an Exemplar:	Yes, Part Number Mx-8-S3OB (APL #10103)
APL:	10103

Organization Name:	Identiv
Name of Product or Service:	Hirsch MX-2 Panel
Part Number:	MX-2
Hardware Version:	7
Software Version:	N/A
Firmware Version:	CCM/CCMx 8.3.00.073/SNIB3 04.01.0384
Has an Exemplar:	Yes, Part Number Mx-8-S3OB (APL #10103)
APL:	10103

Organization Name:	Identiv
Name of Product or Service:	Mx-2 - Hirsch MX controller series with SNIB3 and RREB
Part Number:	Mx-2-S3OB
Hardware Version:	7
Software Version:	N/A
Firmware Version:	CCM/CCMx 8.3.00.73/ SNIB3 4.02.1554
Has an Exemplar:	Yes, Part Number Mx-8-S3OB (APL #10103)
APL:	10103

Organization Name:	Identiv
Name of Product or Service:	Mx-2 - Hirsch MX controller series with SNIB3 and RREB
Part Number:	Mx-2-N3-FICAM
Hardware Version:	7
Software Version:	N/A

Firmware Version:	CCM/CCMx 8.3.00.73/ SNIB3 4.02.1554
Has an Exemplar:	Yes, Part Number Mx-8-S3OB (APL #10103)
APL:	10103

Organization Name:	Identiv
Name of Product or Service:	Mx-1 - Hirsch MX controller series
Part Number:	Mx-1
Hardware Version:	7
Software Version:	N/A
Firmware Version:	CCM/CCMx 8.3.00.73/ SNIB3 4.02.1554
Is an Exemplar:	Yes
APL:	10103

Organization Name:	Identiv
Name of Product or Service:	Mx-1-ME - Hirsch MX controller series
Part Number:	Mx-1-ME
Hardware Version:	7
Software Version:	N/A
Firmware Version:	CCM/CCMx 8.3.00.73/ SNIB3 4.02.1554
Has an Exemplar:	Yes, Part Number Mx-1 (APL #10103)
APL:	10103

Organization Name:	Identiv
Name of Product or Service:	Secure Network Interface Board v3 (SNIB3)
Part Number:	SNIB3
Hardware Version:	3
Software Version:	SNIB3 4.02.1554
Firmware Version:	N/A

Organization Name:	Identiv
Name of Product or Service:	RREB - RS-485 Reader Expansion Board
Part Number:	RREB
Hardware Version:	1
Software Version:	N/A
Firmware Version:	N/A

1.3 Document History

Status	Date	Comments
Approved	2/1/2017	Final Approval Date for PACS Topology 13.02 APL# 10103
Update	2/3/2017	Updated to reflect new part numbering scheme for OSDP readers (PACS Topology 13.02).
Update	9/19/2017	The updated solution includes legacy M2 and M8 controllers.

Update	12/5/2019	The solution was updated to Velocity 3.7 SP2, added MX-1, added Contact ScramblePad reader, and added OSDP Veridt readers.
Update	8/3/2020	Solution updated to Velocity 3.8.1, Added uTrust Contact Readers, updated uTrust Firmware, SNIB3 Firmware, and Controller Firmware.
Update	4/9/2021	Solution updated to Velocity Software, Velocity Cert Check, addition of MX-1-ME
Update	9/21/2021	Update to Velocity 3.8.3 and Cert Service 3.8.3.370
Update	1/13/2022	Update to Velocity Cert Service and controller firmware in preparation for Allegion locksets.
Update	02/02/2024	Update to Velocity Security Management 3.8.5, Velocity Cert Service 3.8.5, and controller and SNIB3 firmware.
Update	02/27/2024	Updated bundled part numbers.
Update	02/11/2025	Updated to Velocity Security Management 3.8.6, Velocity Cert Service 3.8.6, controller firmware and SNIB3 software, and uTrust ScrambleFactor SF.3 Reader Add-on (APL #10196). References to the Hirsch M8 Panel and Hirsch M2 Panel were removed as they have been discontinued for purchase.

1.4 Restrictions:

The Identiv Velocity Security Management System and Velocity Certificate Service solution (APL# **10103**) has been tested and approved as a fully compliant ICAM Solution component. The end-to-end solution components used to test the ICAM compliance of the approved solution are listed below.

**Note: the FIPS 140 certificates (2473, 2425, and 3503) provided with this solution are all of historical status.*

1.4.1 PACS Topology 13.02

- Identiv PIV Reader
 - Identiv uTrust Mullion Reader - OSDP (APL# **10104**)
 - Identiv uTrust Wallmount Reader - OSDP (APL# **10105**)
 - Identiv uTrust Keypad Reader - OSDP (APL# **10106**)
 - Identiv uTrust ScramblePad Reader - OSDP (APL# **10107**)
 - Identiv uTrust Contact TS Reader with Scramblepad – OSDP (APL# **10119**)
 - Identiv uTrust SC Wallmount Contact/Contactless Reader – OSDP (APL# **10124**)

- Identiv uTrust SC Keypad Contact/Contactless Reader - OSDP(APL# **10125**)
- Identiv uTrust ScrambleFactor SF.3 Reader – OSDP (APL # **10196**)
- Veridt PIV Reader
 - Veridt Dual Bio Contact/Contactless Reader (APL# **10092**)
 - Veridt Stealth Dual Contact/Contactless Reader (APL# **10093**)
 - Veridt Stealth Lite Dual Contact/Contactless Reader (APL# **10094**)
 - Veridt Stealth Contactless Reader (APL# **10095**)
 - Veridt Stealth Lite Contactless Reader (APL# **10096**)

Approval of the above product/service indicates your cooperation with the Program and successful testing against a rigorous, comprehensive set of functional requirements derived from government-wide specifications. Testing included positive and negative test cases and threat vectors.

Given the strategic government-wide importance of the APL, the scope and extent of testing performed on your product/service, and the rigor of that testing, the Program would like to acknowledge the noteworthiness of the approval and listing. Your product/service will now be available for procurement to all federal agencies.

Please note that continued listing on the APL requires ongoing conformance to all applicable requirements, including requirements added or amended over time. A listed product/service can become non-conformant for various reasons, including but not limited to:

- New Functional Requirements and Test Cases—The Functional Requirement and Test Case (FRTC) documents are effective immediately. All approved Physical Access Control System (PACS) solutions must pass testing against the new and revised FRTC requirements before the effective date of the new/revised requirements.
- Specific problems are discovered in a vendor's product or services (or class of products/services) after being listed on the APL. The affected vendor(s) are notified that the identified product(s) and services(s) must be improved within the time frames specified in the FRTC, commensurate with the severity level of the problem.
- Updates to testing requirements due to concerns provided to the Evaluation Program by Federal agency buyers.
- Updates to testing requirements due to vendor-provided issues to the Evaluation Program.
- A product whose last certification letter is older than 12 months and has yet to receive the APL Extension approval.

Refer to the applicable Agreements and Program documents for details regarding ongoing compliance, including severity levels and remediation time frames. Products and

services listed as nonconforming will be removed from the APL and added to the Removed Products List (RPL).

If you have any questions, please feel free to contact me.

Matthew Arnold
GSA OGP
(703) 254-6750
Matthew.Arnold@gsa.gov