

FAN screws and spacers assembly



Mounted from PCB top
through FAN hole M3x 3
ex. MFCH34

Mounted from
PCB top


**Spacer sleeve M3 x 3
ex. MECH37**

Mounted from PCB bottom Screw M3 x 3
ex. MECH40

Screw
position
on the FAN

**FAN blowing direction.
Arrow MUST be facing
down (on the PCB)**

FAN wire orientation



Assembly bottom

