


FAN screws and spacers assembly




Mounted from PCB top
through FAN hole M3x 3
ex. MECH34

Mounted from
PCB top

**Spacer sleeve M3 x 3
ex. MFCH37**


Mounted from
PCB bottom Screw M3 x 3
ex. MECH40



Screw
position
on the FAN

FAN blowing direction.
Arrow MUST be facing
down (on the PCB)

FAN wire orientation



Assembly bottom

