


FAN screws and spacers assembly

Mounted from PCB top through FAN hole M3x3
ex. MECH34

Spacer sleeve M3x3
ex. MECH37

Mount from PCB bottom
Screw M3x3
ex. MECH40

FAN orientation and screw position




Screw position
on the FAN

FAN top

FAN blowing direction.
Arrow MUST be facing
down (on the PCB)

FAN wires orientation
FAN wires



Crimp ends with
MECH23, MECH24,
MECH25

PCB

Assembly bottom

