


#### FAN screws and spacers assembly




Mounted from PCB top  
through FAN hole M3x3  
ex. MECH34

Mounted from  
PCB top

**Spacer sleeve M3 x 3  
ex. MECH37**


Mounted from PCB bottom Screw M3 x 3  
ex. MFCH40

#### FAN orientation and screw position



FAN blowing direction.  
Arrow MUST be facing  
down (on the PCB)

### FAN wire orientation



## Assembly bottom

