

QER 12271

QER: POST-SALT 25KM FLGL SF301676C002.01+03- Zeta wires unlocking



Pipe section / Details

Item	Traceability / identification
Project number	SF301676C002
Project name	POST-SALT 25KM FLGL
Pipe section	SF301676C002.01+03
ST number	ST10151958
Affected layer / equipment	Zeta Spiraling
Length affected	911.8m
Drawing number / MP code / STA / Dimension	Zeta wire 6.2 FI09 (MP 205)

Overview of anomaly

Problem Description :-

During the zeta spiraling of POST-SALT 25KM FLGL SF301676C002.01+03 (ST10151958), zeta wire unlocked was detected at length 911.8m on the pipe.

Root Cause :-

The root cause was due to wires entangled in bobbin #05 during running causing wire damage and wire unlock at laying point.

Problem Handling:-

Reparation by un-spiral has been performed to re-position the wires to be in a good spiral. Thus, this reparation was accepted as it is and the dimensional after the repair is within the criteria.

DEFECT PHOTO



Figure 1 : Zeta wire unlocked was detected at length 911.8m on the pipe.

PHOTO AFTER REPAIRED





Figure 2 : Reparation by un-spiral has been performed to re-position the wires to be in a good spiral. Thus, this reparation was accepted as it is and the dimensional after the repair is within the criteria.

THANK YOU

