

HCA HLL

Ghana

23 June 2023

Name	D	t	PRH	Wind	Kts	Limitation	Non Compliances	
FPSO Kwame Nkrumah MV21	21	12.8	3 1		0-15	PPSO Overflight of outboard foam monitor platform to be avoided on take-off Aiming circle offset Possible turbulence from turbine exhaust mid-ships and funnel on inboard side of helideck No Dgs to be uplifted	5:1 Miso	- management of the control of the c
Prof. John Evans Atta Mills	20.8	8 12.8	3 1			 FPSO Table 1 (T) applies if Overflight of 5:1 items unavoidable Possible turbulence from turbine exhaust mid-ships, funnel, boiler exhaust on inboard side of helideck. Possible turbulence from radio room structure. Turbulence reports requested. 	210' 5:1	Davit crane on port bridge wing if not locked in securing position Foam monitor platforms infringe sector. Approx 4.20m from edge of SLA. Various deck structures below helideck port forward and starboard aft