

MODEL PAPER

TED (15) 6112

Reg No:.....

REVISION-2015

Signature:.....

**SIXTH SEMESTER DIPLOMA EXAMINATION IN TOOL AND DIE
ENGINEERING**

TOOL DESIGN

[Time: 3 hours

(Maximum marks: 100)

Marks

PART – A

(Maximum marks: 10)

I. (Answer the following questions in one or two sentences. Each question carries 2 marks)

1. List the types of guide plate.
2. State the function of stock lifter.
3. Define parting operation.
4. State about forming operation.
5. Define the term flash in a compression mould.

(5x2=10)

PART – B

(Maximum marks: 30)

II. (Answer any *five* of the following questions. Each question carries 6 marks.)

1. Explain the fine blanking process with sketch.
2. List down the application of guide plate tools.
3. Reproduce the detailed view of a parting off tool.
4. Explain about V-Bending operation with sketch.
5. List down the types of form dies.
6. Explain about stripper plate ejection method used in an injection mould with sketch.
7. Differentiate cold chamber die casting method with hot chamber die casting method.

(5 X 6 = 30)

P.T.O

PART – C

(Answer one full question from each unit. Each full question carries 15 marks.)

UNIT – I

- III. a. Show the detailed view of a progressive guide plate tool. (9)
b. State the advantages of die set assembly. (6)

OR

- IV. a. Explain the elements of fine blanking tool. (8)
b. Show the detailed view of a die set assembly. (7)

UNIT – II

- V. a. Show the detailed view of a progressive tool incorporating fixed stop. (8)
b. Explain about the working of automatic stop with sketch. (7)

OR


- VI. a. Describe about cut off tool with sketch. (8)
b. Explain about fixed stripper with sketch. (7)

UNIT – III

- VII. a. Explain about U-Bending tool with sketch. (8)
b. Explain about deep drawing process with sketch. (7)

OR

- VIII. a. Draw the detailed view of a compound tool with indirect knock out. (8)
b. Calculate the blank diameter to make the shell shown in the figure given below. (7)



UNIT-IV

- IX. a. Show the detailed view of a multi cavity injection mould. (9)
b. Show the view of compression mould showing horizontal flash. (6)

OR

- X. a. Illustrate the submerged plunger hot chamber die casting method. (9)
b. Explain about the sprue gate with sketch. (6)