Pscudo Code

Initialize the required register and the relevent Pins using TRIS:× and LAT.×

Have Pin RA7 Set to ON at all times

1

Start a loop to start

the Counting the 6-bit

numbers Whenever push button is hit

Reset the counter before it exceeds 6-bit limit.

Schematic

