Pscudo Code

Initialize the required register and the relevent Pins using TRIS.x and LAT.x

Have Pin RA7 Set to ON at all times

1

Start a loop to start the Counting the 6-bit numbers.

1

Delay 250ms after each count and reset counter when counter reaches 6-bits.

Schematic

