
BASIC ARC AND GAS WELDING SYMBOLS

Type of Weld			
Groove Bead	Groove Fillet	Groove Square	Groove "V"
Groove Bevel	Groove "U"	Groove "J"	Plug & Slot
	\ \ \		
Field Weld	Weld All Around	Flush	

- In plan or elevation, near, far, and both sides, locations refer to nearest member parallel to plane of drawing and not to others farther behind.
- 2. In section or end views only, when weld is not drawn, the side to which arrow points is considered near side.
- 3. Welds on both sides are of same size unless otherwise shown.
- Symbols govern to break in continuity of structure or to extent of hatching or dimension lines.



- 5. Tail of arrow used for specification reference.
- 6. All welds are continuous and of user's standard propertions and all except V-grooved and bevel-grooved welds are closed unless otherwise shown.
- 7. When welds are drawn in section or end views, obvious information is not given by symbol.
- 8. In joints in which one member only is to be grooved, arrows point to that member.