

Highlight Catch and Finding After Model Go Live




Plant : Co-Gen Thermal Plant 130MW
Machine : GT12
Model : Mechanical
Event : Lube oil supply temperature was

detected abnormally high than predicted value on 28 April 2022.

Action : Although the temperature was still lower than interlock setpoint recommended by OEM, running the machine at too high lube oil temperature could shorten bearing lifetime. Then O&M investigated related equipment condition and found that cooling water flow had been improperly adjusted. After cooling flow valve position was well set, lube oil temperature returned to normal value as predicted by the model.

Saving : This lube oil is supplied to 9 sets of bearings at gas turbine, gearbox and generator. Timely correction on abnormally high lube oil temperature has saved unnecessary bearing replacement at cost approx. 0.2MUSD.



Before

After