Field service report
Asset: BLR-01 (Boiler 1) Date: 2026-08-04 Technician: Lena Fischer
Replaced 2 thermocouples. Burner still trips on high limit.
Needs a return visit with a combustion analyzer.
Downtime so far: 6 hours.