
System Dynamics and Control 1 Stabi

Stability





HCM City Univ. of Technology, Faculty of Mechanical Engineering

Nguyen Tan Tien

System Dynamics and Control

Stability

Learning Outcome

After completing this chapter, the student will be able to

- Make and interpret a basic Routh table to determine the stability of a system
- Make and interpret a Routh table where either the first element of a row is zero or an entire row is zero
- Use a Routh table to determine the stability of a system represented in state space

HCM City Univ. of Technology, Faculty of Mechanical Engineering

Nguyen Tan Tien

System Dynamics and Control

3 Stabil

§1. Introduction

- Three requirements enter into the design of a control system
- · transient response
- · stability, and
- · steady-state errors
- Stability is the most important system specification. If a system is unstable, transient response and steady-state errors are moot points. An unstable system cannot be designed for a specific transient response or steady-state error requirement
- What, then, is stability? There are many definitions for stability, depending upon the kind of system or the point of view. In this section, discussion is limited to linear, time-invariant (LTI) systems

System Dynamics and Control

Stability

§1.Introduction

 The output of a system can be controlled if the steady-state response consists of only the forced response. But the total response of a system is the sum of the forced and natural responses, or

$$c(t) = c_{forced}(t) + c_{natural}(t) \label{eq:constraint}$$

- There are two definitions for stability, using
- the natural response, and
- the total response (BIBO)

HCM City Univ. of Technology, Faculty of Mechanical Engineering

Nguven Tan Tien

HCM City Univ. of Technology, Faculty of Mechanical Engineering

Nguyen Tan Tien

System Dynamics and Control

Cto.

§1.Introduction

- Consider the general TF

$$G(s) = \frac{R(s)}{C(s)} = \frac{b_m s^m + b_{m-1} s^{m-1} + \dots + b_0}{a_n s^n + a_{n-1} s^{n-1} + \dots + a_1 s + a_0} = \frac{N(s)}{D(s)}$$

The response

$$c(t) = c_{forced}(t) + c_{natural}(t)$$

 $c_{forced}(t)$: the forced response

 $c_{natural}(t)$: the natural response $c_{natural}(t) = \sum_{i=1}^{n} \lambda_i e^{p_i t}$

 p_i : the poles of the system, or the roots of D(s) = 0

The system is

- stable if $\lim c_{natural}(t) \to 0$
- unstable if $\lim_{t\to\infty} c_{natural}(t) \to \infty$

System Dynamics and Control

6 St

§1.Introduction

- Using the natural response, a linear, time-invariant system is
- stable if the natural response approaches zero as time approaches infinity
- unstable if the natural response approaches infinity as time approaches infinity
- marginally stable if the natural response neither decays nor grows but remains constant or oscillates
- Using the total response (BIBO), a linear, time-invariant system is
- stable if every bounded input yields a bounded output
- unstable if any bounded input yields an unbounded output

HCM City Univ. of Technology, Faculty of Mechanical Engineering

Nguyen Tan Tien

HCM City Univ. of Technology, Faculty of Mechanical Engineering

§1. Introduction

- How do we determine if a system is stable?

Poles placed in the left half-plane (LHP)

Poles placed in LHP yield either pure exponential decay or damped sinusoidal natural responses. These natural responses decay to zero as $t \to \infty$

→ if the closed-loop system poles are in the LHP and hence have a negative real part, the system is stable

Poles in the right half-plane (RHP)

Poles in RHP yield either pure exponentially increasing or exponentially increasing sinusoidal natural responses. These natural responses approach infinity as $t \to \infty$

→ if the closed-loop system poles are in the RHP and hence have a positive real part, the system is unstable

HCM City Univ. of Technology, Faculty of Mechanical Engineering

Nguyen Tan Tien

System Dynamics and Control

Stabil

§2. Routh-Hurwitz Criterion

- Routh-Hurwitz criterion for stability (Routh, 1905)
- · Generate a data table called a Routh table, and
- Interpret the Routh table to tell how many closed-loop system poles are in LHP, RHP, and on the $j\omega$ -axis
- Why study the Routh-Hurwitz criterion when modern calculators and computers can tell us the exact location of system poles?
- The power of the method lies in design rather than analysis.
 For example, it is easy to determine the range of the unknown parameter in the denominator of a TF to yield stability

HCM City Univ. of Technology, Faculty of Mechanical Engineering

Nguyen Tan Tien

Creating a Routh Table

System Dynamics and Control

§2. Routh-Hurwitz Criterion

Generating a Basic Routh Table

- Look at the equivalent closed-loop TF

$$\frac{R(s)}{a_n s^n + a_{n-1} s^{n-1} + \dots + b_0} \frac{C(s)}{a_n s^n + a_{n-1} s^{n-1} + \dots + a_1 s + a_0}$$

- Create the Routh table

s^n	a_n	a_{n-2}	a_{n-4}	•••
s^{n-1}	a_{n-1}	a_{n-3}	a_{n-5}	•••
s^{n-2}	a_{n-1}	a_{n-1}	$b_3 = \cdots$	
s^{n-3}	$c_1 = \frac{- \begin{vmatrix} a_{n-1} & a_{n-3} \\ b_1 & b_2 \end{vmatrix}}{b_1}$	$c_2 = \frac{- \begin{vmatrix} a_{n-1} & a_{n-5} \\ b_1 & b_3 \end{vmatrix}}{b_1}$	$c_3 = \cdots$	
s ⁰		0		

HCM City Univ. of Technology, Faculty of Mechanical Engineering

Nguven Tan Tien


System Dynamics and Control

10

§2. Routh-Hurwitz Criterion

- <u>Ex.6.1</u>

Make the Routh table for the system



Solution

Find the equivalent closed-loop system

Create the Routh table

10	- 110	Julii labic		
	s^3	1	31	0
	s^2	10	1030	0
	s^1	$\frac{-\begin{vmatrix} 1 & 31\\ 10 & 1030 \end{vmatrix}}{10} = -72$	$\frac{-\begin{vmatrix} 1 & 0 \\ 10 & 0 \end{vmatrix}}{10} = 0$	
	s ⁰	$\frac{-\begin{vmatrix} 10 & 1030 \\ -72 & 0 \end{vmatrix}}{-72} = 1030$,

HCM City Univ. of Technology, Faculty of Mechanical Engineering

Nguven Tan Tien

System Dynamics and Control

§2. Routh-Hurwitz Criterion


Interpreting the Basic Routh Table

- Routh-Hurwitz criterion

number of roots in the RHP = number of sign changes in the first column

- Ex. two sign changes in the first column two poles exist in the RHP

 \Rightarrow the system is unstable



HCM City Univ. of Technology, Faculty of Mechanical Engineering

Nguyen Tan Tien

System Dynamics and Control

12

§2. Routh-Hurwitz Criterion

Note

For convenience, any row of the Routh table can be multiplied by a positive constant without changing the values of the rows below



HCM City Univ. of Technology, Faculty of Mechanical Engineering

§2. Routh-Hurwitz Criterion

Skill-Assessment Ex.6.1

Problem Make a Routh table and tell how many roots of the wileyPLUS following polynomial are in the RHP and in the LHP $P(c) = 36^7 + 96^6 + 66^5 + 46^4 + 76^3 + 86^2 + 364$

 $P(s) = 3s^7 + 9s^6 + 6s^5 + 4s^4 + 7s^3 + 8s^2 + 2s + 6$

Solution Create the Routh table

s^7	3	6	7	2	0
s ⁶	9	4	8	6	
s ⁵	14 3	39	0	0	0
s ⁴	$-\frac{61}{14}$	8	6	0	0
s^3	$\frac{787}{61}$	$\frac{392}{61}$	0	0	

HCM City Univ. of Technology, Faculty of Mechanical Engineering

Nguyen Tan Tien

System Dynamics and Control §2. Routh-Hurwitz Criterion

> 14 39 s^5 0 0 9 61 8 0 6 0 14 787 392 s^3 0 0 61 61 8004 s^2 6 0 787 1581 s^1 0 1334

→ Four poles in the RHP and three poles in the LHP

 $P(s) = 3s^7 + 9s^6 + 6s^5 + 4s^4 + 7s^3 + 8s^2 + 2s + 6$

s⁰

HCM City Univ. of Technology, Faculty of Mechanical Engineering

System Dynamics and Control

§3. Routh-Hurwitz Criterion: Special Cases

Zero Only in the First Column

- An epsilon, ε , is assigned to replace the zero in the first column. The value ε is then allowed to approach zero from either the positive or the negative side, after which the signs of the entries in the first column can be determined

15

- Ex.6.2 Stability via Epsilon Method

Determine the stability of the closed-loop TF

$$T(s) = \frac{10}{s^5 + 2s^4 + 3s^3 + 6s^2 + 5s + 3}$$

Solution

s ⁵	1	3	5
s^4	2	6	3
s³	$\frac{-\begin{vmatrix} 1 & 3 \\ 2 & 6 \end{vmatrix}}{2} = 0$	$\frac{-\begin{vmatrix} 1 & 5 \\ 2 & 3 \end{vmatrix}}{2} = -3.5$	$\frac{-\begin{vmatrix} 1 & 0 \\ 2 & 0 \end{vmatrix}}{2} = 0$

HCM City Univ. of Technology, Faculty of Mechanical Engineering

Nguyen Tan Tien

Stability

System Dynamics and Control §3. Routh-Hurwitz Criterion: Special Cases

s⁴ s^3 s^2 $42\varepsilon - 49 - 6\varepsilon$ $12\varepsilon - 14$

HCM City Univ. of Technology, Faculty of Mechanical Engineering

Nguyen Tan Tien

System Dynamics and Control §3. Routh-Hurwitz Criterion: Special Cases

Label First column s⁴ 2 s^3 $6\varepsilon - 7$ s^2 $42\varepsilon - 49 - 6\varepsilon^2$ s^1 + $12\varepsilon - 14$

The system is unstable and has two poles in the RHP

System Dynamics and Control §3. Routh-Hurwitz Criterion: Special Cases

Trylt 6.1 Use the following MATLAB statement to find the poles of the closed-loop transfer function in Eq. (6.2)

$$T(s) = \frac{10}{s^5 + 2s^4 + 3s^3 + 6s^2 + 5s + 3}$$
 (6.2)

roots([1 2 3 6 5 3])

HCM City Univ. of Technology, Faculty of Mechanical Engineering

Nguyen Tan Tien

HCM City Univ. of Technology, Faculty of Mechanical Engineering

§3. Routh-Hurwitz Criterion: Special Cases



Run ch6sp1 in Appendix F

Learn how to use MATLAB to

- · use MATLAB to calculate the values of cells in a Routh table even if the table contains symbolic objects, such as ε
- see that the Symbolic Math Toolbox and MATLAB yield an alternate way to generate the Routh table for Ex.6.2

System Dynamics and Control

§3. Routh-Hurwitz Criterion: Special Cases

Zero Only in the First Column - Alternative method (Phillips, 1991)

Stability via Reverse Coefficients

Determine the stability of the closed-loop TF

$$T(s) = \frac{10}{s^5 + 2s^4 + 3s^3 + 6s^2 + 5s + 3}$$
 (6.6)

Solution

Write a polynomial that has the reciprocal roots of the denominator of Eq. (6.6)

$$s^{5} + 2s^{4} + 3s^{3} + 6s^{2} + 5s + 3$$

$$D(s) = 3s^{5} + 5s^{4} + 6s^{3} + 3s^{2} + 2s + 1$$
(6.7)

HCM City Univ. of Technology, Faculty of Mechanical Engineering

Nguyen Tan Tien

HCM City Univ. of Technology, Faculty of Mechanical Engineering

Nguyen Tan Tien

System Dynamics and Control

§3. Routh-Hurwitz Criterion: Special Cases

$$s^{5} + 2s^{4} + 3s^{3} + 6s^{2} + 5s + 3$$

$$D(s) = 3s^{5} + 5s^{4} + 6s^{3} + 3s^{2} + 2s + 1$$
(6.7)

Form the Routh table using Eq. (6.7)

s ⁵	3	6	2
s ⁴	5	3	1
s ³	4.2	1.4	
s^2	1.33	1	
s ¹	-1.75		
S ⁰	1		

Since there are two sign changes, the system is unstable and has two right-half-plane poles

This is the same as the result obtained in Ex.6.2. Notice that the above table does not have a zero in the first column

HCM City Univ. of Technology, Faculty of Mechanical Engineering

Nguyen Tan Tien

System Dynamics and Control

§3. Routh-Hurwitz Criterion: Special Cases Entire Row is Zero

- Ex.6.4 Stability via Routh Table with Row of Zeros

Determine the number of RHP poles in the closed-loop TF 10

Replace all row of zeros by $P(s) = s^4 + 6s^2 + 8$ Differentiate P(s) with respect to s $dP(s)/ds = 4s^3 + 12s + 0$

HCM City Univ. of Technology, Faculty of Mechanical Engineering

RHP

poles

System Dynamics and Control

§3. Routh-Hurwitz Criterion: Special Cases

Pole Distribution via Routh Table with Row of Zeros Determine the position of the TF

$$T(s) = \frac{20}{s^8 + s^7 + 12s^6 + 22s^5 + 39s^4 + 59s^3 + 48s^2 + 38s + 20}$$

Solution	

s^8			1			12		39		48	20
s^7			1			22		59		38	0
s ⁶		-1	-10		-2	- 20	1	10	2	20	0
s ⁵		1	20		3	60	2	40		0	0
s ⁴			1			3		2		0	0
s ³	2	4	0	3	6	0	0	0		0	0
s ²		3	3/2		4	2		0		0	0
s^1			1/3			0		0		0	0
s ⁰			4			0		0		0	0

HCM City Univ. of Technology, Faculty of Mechanical Engineering

Nguyen Tan Tien

System Dynamics and Control

§3. Routh-Hurwitz Criterion: Special Cases

Interpreting the Routh table

- The sub-polynomial $P(s) = s^4 + 3s^2 + 2 = (s^2 + 1)(s^2 + 2) =$ 0 has 4 imaginary roots \rightarrow 4 poles on the $j\omega$ -axis
- Two signs changed in the first column → 2 poles on RHP

• 2 poles on LHP

s ⁸			1			12		39		48	20
s ⁷			1			22		59		38	0
s ⁶		-1	-10		-2	-20	1	10	2	20	0
s^5		1	20		3	60	2	40		0	0
s ⁴			1			3		2		0	0
s3	2	4	0	3	6	0	0	0		0	0
s2		3	3/2		4	2		0		0	0
s^1			1/3			0		0		0	0
s^0			4			0		0		0	0

HCM City Univ. of Technology, Faculty of Mechanical Engineering

25

§3. Routh-Hurwitz Criterion: Special Cases

Skill-Assessment Ex.6.2

Problem Find how many poles of the following closed-loop system, T(s), are in the RHP, LHP, and on the jω-axis

$$T(s) = \frac{s^3 + 7s^2 - 21s + 10}{s^6 + s^5 - 6s^4 - s^2 - s + 6}$$

Solution Create the Routh table

s ⁶	1	-6	-1	6
s ⁵	1	0	-1	0
s ⁴	-6	0	6	0
s^3	-24 0	0	0	0
s^2	εθ	6	0	0
s^1	$\frac{144}{\varepsilon}$	0	0	0
s	6	0	0	0

HCM City Univ. of Technology, Faculty of Mechanical Engineering

Nguyen Tan Tien

System Dynamics and Control

26

Stability

§3. Routh-Hurwitz Criterion: Special Cases

Interpreting the Routh table

- $P(s) = -6s^4 + 6 = -6(s^2 + 1)(s^2 1) = 0$ has 2 imaginary roots \rightarrow 2 poles on the $j\omega$ -axis
- There is two sign change in the first column \rightarrow the polynomial has two RHP pole
- Two left poles in the LHP

s ⁶	1	-6	-1	6
s^5	1	0	-1	0
s ⁴	-6	0	6	0
	-24 0	0	0	0
s^2	εθ	6	0	0
s^1	$\frac{144}{\varepsilon}$	0	0	0
s^0	6	0	0	0

HCM City Univ. of Technology, Faculty of Mechanical Engineering

Maureon Ton Tion

System Dynamics and Control

27


§4. Routh-Hurwitz Criterion: Additional Examples

Ev 6 6

Standard Routh-Hurwitz

Find the number of poles in the LHP, the RHP, and on the $j\omega$ -axis for the system





The closed-loop TF

$$T(s) = \frac{200}{s^4 + 6s^3 + 11s^2 + 6s + 200)}$$

The Routh table for the denominator

s^4		1		11	200
s^3	1	6	1	6	
s^2	1	10	20	200	
s^1		-19			
c ⁰		20			

HCM City Univ. of Technology, Faculty of Mechanical Engineering

Nauven Tan Tier

§4. Routh-Hurwitz Criterion: Additional Examples

Interpreting the Routh table

No zero row

System Dynamics and Control

- \rightarrow there is no pole on the $j\omega$ -axis
- There is two sign change in the first column
 - \rightarrow the polynomial has two RHP pole
- The system has 4 poles
 - → two left poles in the LHP

s4		1		11	200
s ³	1	6	1	6	
s ²	1	10	20	200	
s^1		-19			
s ⁰		20			

HCM City Univ. of Technology, Faculty of Mechanical Engineering

Nguyen Tan Tien

System Dynamics and Control

20

§4. Routh-Hurwitz Criterion: Additional Examples

- Ev 6 7 D

Routh-Hurwitz with Zero in First Column

Find the number of poles in the LHP, the RHP, and on the $j\omega$ -axis for the system

$$\begin{array}{c|c} R(s) & E(s) & 1 & C(s) \\ \hline & s(2s^4 + 3s^3 + 2s^2 + 3s + 2) & & & \end{array}$$

Solution

The closed-loop TF

$$T(s) = \frac{\frac{1}{s(2s^4 + 3s^3 + 2s^2 + 3s + 2)}}{1 + \frac{1}{s(2s^4 + 3s^3 + 2s^2 + 3s + 2)}}$$
$$= \frac{1}{2s^5 + 3s^4 + 2s^3 + 3s^2 + 2s + 1}$$

HCM City Univ. of Technology, Faculty of Mechanical Engineering

Nguyen Tan Tien

System Dynamics and Control 30 §4. Routh-Hurwitz Criterion: Additional Examples

The Routh table for the denominator

s ⁵	2	2	2
s4	3	3	1
s ⁵ s ⁴ s ³	εθ	4/3	
s ²	$\frac{3\varepsilon - 4}{\varepsilon}$	1	
s^1	$\frac{12\varepsilon - 16 - 3\varepsilon^2}{9\varepsilon - 12}$		
s ⁰	1		
	2-	. 10-	16 2-2

$$0 < \varepsilon \ll 1 \rightarrow \frac{3\varepsilon - 4}{\varepsilon} < 0, \frac{12\varepsilon - 16 - 3\varepsilon^2}{9\varepsilon - 12} >$$

There are two sign changes, and the system is unstable, with two poles in the RHP. The remaining poles are in the LHP

 $T(s) = \frac{1}{2s^5 + 3s^4 + 2s^3 + 3s^2 + 2s + 1}$

HCM City Univ. of Technology, Faculty of Mechanical Engineering

§4. Routh-Hurwitz Criterion: Additional Examples

Alternative solution using the reciprocal roots

There are two sign changes, and the system is unstable, with two poles in the RHP. The remaining poles are in the LHP

 $T(s) = \frac{1}{2s^5 + 3s^4 + 2s^3 + 3s^2 + 2s + 1}$

HCM City Univ. of Technology, Faculty of Mechanical Engineering

Nguyen Tan Tien

System Dynamics and Control

§4. Routh-Hurwitz Criterion: Additional Examples

Run ch6p1 in Appendix B Learn how to use MATLAB to

- perform block diagram reduction to find T(s), followed by an evaluation of the closed-loop system's poles to determine stability
- do Ex.6.7

HCM City Univ. of Technology, Faculty of Mechanical Engineering

Nguyen Tan Tien

System Dynamics and Control

33

§4. Routh-Hurwitz Criterion: Additional Examples

- Ex.6.8

Routh-Hurwitz with Row of Zeros

Find the number of poles in the LHP, the RHP, and on the $j\omega$ axis for the system

$$\underbrace{ \begin{array}{c|c} R(s)_+ \\ \hline \\ s(s^7 + 3s^6 + 10s^5 + 24s^4 + 48s^3 + 96s^2 + 128s + 192) \end{array} }^{C(s)}$$

Solution

The closed-loop TF

$$T(s) = \frac{G(s)}{1 + G(s)}$$

$$= \frac{128}{s^8 + 3s^7 + 10s^6 + 24s^5 + 48s^4 + 96s^3 + 128s^2 + 192s + 128}$$

HCM City Univ. of Technology, Faculty of Mechanical Engineering

Nguven Tan Tien

System Dynamics and Control

§4. Routh-Hurwitz Criterion: Additional Examples The Routh table for the denominator

s ⁸			1			10			48			128	128
s ⁷		1	3		8	24		32	96		64	192	
s ⁶		1	2		8	16		32	64		64	128	
s ⁵	3	6	θ	16	32	0	32	64	0	0	0	0	
s ⁴		1	8/3		8	64/3		24	64				
s ³		-1	-8		-5	-40							
s2		1	3		8	24							
s^1			3										
s			8										
	$P(s) = s^6 + 8s^4 + 32s^2 + 64$												

$$dP(s)/ds = 6s^5 + 32s^3 + 64s + 0$$

 $T(s) = \frac{120}{s^8 + 3s^7 + 10s^6 + 24s^5 + 48s^4 + 96s^3 + 128s^2 + 192s + 128)}$ HCM City Univ. of Technology. Faculty of Mechanical Engineering

Nguven Tan Tien

System Dynamics and Control

§4. Routh-Hurwitz Criterion: Additional Examples Interpreting the Routh table

s^8			1			10			48			128	128
s ⁷		1	3		8	24		32	96		64	192	
s ⁶		1	2		8	16		32	64		64	128	
s ⁵	3	6	0	16	32	0	32	64	0	0	0	0	
s ⁴		1	8/3		8	64/3		24	64				
s³		-1	-8		-5	-40							
s ²		1	3		8	24							
s^1			3										
s ⁰			8										

- $P(s) = (s^4 + 4s^2 + 16)(s^2 + 4) \rightarrow 2$ poles on the $j\omega$ -axis
- Two sign change in the first column → 2 RHP pole
- The system has 8 poles → left poles in the LHP

HCM City Univ. of Technology, Faculty of Mechanical Engineering


Nguyen Tan Tien

System Dynamics and Control

§4. Routh-Hurwitz Criterion: Additional Examples

Trylt 6.2

Use MATLAB, The Control System Toolbox, and the following statements to find the closed-loop transfer function, T(s), for Ex.6.8 and the closed-loop poles



numg=128; deng=[1 3 10 24 48 96 128 192 0]; G=tf(numg,deng); T=feedback(G,1) poles=pole(T)

HCM City Univ. of Technology, Faculty of Mechanical Engineering

§4. Routh-Hurwitz Criterion: Additional Examples

- Ex.6.9

Stability Design via Routh-Hurwitz

Find the number of poles in the LHP, the RHP, and on the $j\omega$ axis for the system

$$R(s)$$
 $E(s)$
 $S(s+7)(s+11)$
 $C(s)$

Solution

The closed-loop TF

$$T(s) = \frac{\frac{K}{s(s+7)(s+11)}}{1 + \frac{K}{s(s+7)(s+11)}} = \frac{K}{s^3 + 18s^2 + 77s + K}$$

HCM City Univ. of Technology, Faculty of Mechanical Engineering

Nguyen Tan Tien

System Dynamics and Control

§4. Routh-Hurwitz Criterion: Additional Examples

The Routh table for the denominator

s^3	1	77
s ²	18	K
s^1	$\frac{1386 - K}{18}$	
s^0	K	

• *K* > 1386

the system is unstable

• *K* < 1386 • K = 1386 the system is stable

1386

 $P(s) = 18s^2 + 1386$: 2 poles in the $j\omega$ -axis, 1 pole in the LHP

$$T(s) = \frac{K}{s^{3+10s^{2}+77s+K}}$$

HCM City Univ. of Technology, Faculty of Mechanical Engineering

System Dynamics and Control

§4. Routh-Hurwitz Criterion: Additional Examples

Run ch6p2 in Appendix B

Learn how to use MATLAB to

- set up a loop to search for the range of gain to yield stability
- do Ex.6.9

System Dynamics and Control

§4. Routh-Hurwitz Criterion: Additional Examples

Learn how to use the Symbolic Math Toolbox to

- run ch6sp2 in Appendix F
- · calculate the values of cells in a Routh table even if the table contains symbolic objects, such as a variable gain, K
- solve Ex.6.9

HCM City Univ. of Technology, Faculty of Mechanical Engineering

Nguyen Tan Tien

HCM City Univ. of Technology, Faculty of Mechanical Engineering

Nguyen Tan Tien

System Dynamics and Control

§4. Routh-Hurwitz Criterion: Additional Examples

The Routh-Hurwitz criterion is often used in limited applications to factor polynomials containing even factors

Factoring via Routh-Hurwitz

Factor the polynomial $P_0(s) = s^4 + 3s^3 + 30s^2 + 30s + 200$

Solution The Routh table

s^4		1		30	200
s^3	1	3	10	30	
s²	1	20	10	200	0
s ¹	2	0	0	0	0
s ⁰		10			0

From the zero row $P(s) = s^2 + 10$, then

$$P_0(s) = s^4 + 3s^3 + 30s^2 + 30s + 200$$

= $(s^2 + 10)(s^2 + 3s + 20)$

$$= (s + j3.1623)(s - j3.1623)$$

$$\times (s + 15 + j4.213)(s + 15 - j4.213)$$

HCM City Univ. of Technology, Faculty of Mechanical Engineering

System Dynamics and Control

Stability

§4. Routh-Hurwitz Criterion: Additional Examples

Skill-Assessment Ex.6.3

Problem For a unity feedback system with the forward TF

WPCS Control Solutions $G(s) = \frac{K(s+20)}{s(s+2)(s+3)}$

find the range of K to make the system stable

Solution The closed-loop TF

$$T(s) = \frac{G(s)}{1 + G(s)} = \frac{K(s + 20)}{s^3 + 5s^2 + (6 + K)s + 20K}$$
The Routh table

The system is stable $\frac{1}{s^2}$ 30 - 15K > 0 $\begin{cases} 20K > 0 \end{cases}$ $\rightarrow 0 < K < 2$ 20K

HCM City Univ. of Technology, Faculty of Mechanical Engineering

§5. Stability in State Space

- The system transfer function

$$\begin{split} T(s) &= C(sI - A)^{-1}B + D \\ &= C\frac{\operatorname{adj}(sI - A)}{\det(sI - A)}B + D \\ &= \frac{N(s)}{\det(sI - A)} \end{split}$$

The characteristic equation det(sI - A) = 0

- The eigenvalues of the matrix A are identical to the system's poles before cancellation of common poles and zeroes in the TF
- → the stability of a system represented in state space can be determined by finding the eigenvalues of the system matrix, A, and determining their locations on the s-plane

HCM City Univ. of Technology, Faculty of Mechanical Engineering

Nguyen Tan Tien

System Dynamics and Control

§5. Stability in State Space

- Ex.6.11

Stability in State Space

Given the system

$$\dot{x} = \begin{bmatrix} 0 & 3 & 1 \\ 2 & 8 & 1 \\ -10 & -5 & -2 \end{bmatrix} x + \begin{bmatrix} 10 \\ 0 \\ 0 \end{bmatrix} u, y = \begin{bmatrix} 1 & 0 & 0 \end{bmatrix} x$$

find out how many poles are in the LHP, in the RHP, and on the jω-axis

Solution

Find
$$(sI - A)$$

$$sI - A = \begin{bmatrix} s & 0 & 0 \\ 0 & s & 0 \\ 0 & 0 & s \end{bmatrix} - \begin{bmatrix} 0 & 3 & 1 \\ 2 & 8 & 1 \\ -10 & -5 & -2 \end{bmatrix}$$

$$= \begin{bmatrix} s & -3 & -1 \\ -2 & s - 8 & -1 \\ 10 & 5 & s + 2 \end{bmatrix}$$

HCM City Univ. of Technology, Faculty of Mechanical Engineering

System Dynamics and Control

§5. Stability in State Space

The Dynamics and Control 45 Stability Stability in State Space
$$\det(s\textbf{\textit{I}}-\textbf{\textit{A}}) = \det\begin{bmatrix} s & -3 & -1 \\ -2 & s-8 & -1 \\ 10 & 5 & s+2 \end{bmatrix} \\ = s \begin{vmatrix} s-8 & -1 \\ 5 & s+2 \end{vmatrix} - (-3) \begin{vmatrix} -2 & -1 \\ 10 & s+2 \end{vmatrix} \\ + (-1)s \begin{vmatrix} -2 & s-8 \\ 10 & 5 \end{vmatrix} \\ = s^3 - 6s^2 - 7s - 52$$

Using this polynomial, form the Routh table

s^3	, ·	1		-7
s ²	-3	-6	-26	-52
s^1	-1	-47/3	0	0
-0		26		

One sign change in the first column, the system has one RHP pole and two LHP poles. It is therefore unstable

HCM City Univ. of Technology, Faculty of Mechanical Engineering

Nguyen Tan Tien

System Dynamics and Control

§5. Stability in State Space MATLAB

Learn how to use MATLAB to

- run ch6sp3 in Appendix B
- · determine the stability of a system represented in state space by finding the eigenvalues of the system matrix
- do Ex.6.11

HCM City Univ. of Technology, Faculty of Mechanical Engineering

Nguven Tan Tien

System Dynamics and Control

§5. Stability in State Space

Skill-Assessment Ex.6.4

Problem For the following system represented in state space, find out how many poles are in the LHP, in the RHP, WPCS and on the $j\omega$ -axis

Control Solutions

on the *jw*-axis
$$\dot{x} = \begin{bmatrix} 2 & 1 & 1 \\ 1 & 7 & 1 \\ -3 & 4 & -5 \end{bmatrix} x + \begin{bmatrix} 0 \\ 0 \\ 1 \end{bmatrix} r, y = \begin{bmatrix} 0 & 1 & 0 \end{bmatrix} x$$

Solution Find |sI - A|

$$sI - A = \begin{bmatrix} s & 0 & 0 \\ 0 & s & 0 \\ 0 & 0 & s \end{bmatrix} - \begin{bmatrix} 2 & 1 & 1 \\ 1 & 7 & 1 \\ -3 & 4 & -5 \end{bmatrix}$$
$$= \begin{bmatrix} s - 2 & -1 & -1 \\ -1 & s - 7 & -1 \\ 3 & -4 & s + 5 \end{bmatrix}$$
$$det(sI - A) = s^3 - 4s^2 - 33s + 51$$

HCM City Univ. of Technology, Faculty of Mechanical Engineering

Nguyen Tan Tien

System Dynamics and Control

§5. Stability in State Space

 $\det(sI - A) = s^3 - 4s^2 - 33s + 51$ Form the Routh table

s^3	1	-33
s ²	-4	51
s^1	-20.25	
_0	F1	

There are two sign changes. Thus, there are two RHP poles and one LHP pole

HCM City Univ. of Technology, Faculty of Mechanical Engineering

Stability

System Dynamics and Control

System Dynamics and Control §6. Case Studies

§5. Stability in State Space

Trylt 6.3 Use the following MATLAB statements to find the eigenvalues of the system described in Skill-Assessment Ex.6.4
$$\dot{x} = \begin{bmatrix} 2 & 1 & 1 \\ 1 & 7 & 1 \\ -3 & 4 & -5 \end{bmatrix} x + \begin{bmatrix} 0 \\ 0 \\ 1 \end{bmatrix} r$$

HCM City Univ. of Technology, Faculty of Mechanical Engineering

Nguyen Tan Tien

Stability

HCM City Univ. of Technology, Faculty of Mechanical Engineering