

Statement of Work (SOW)

USCGC MOHAWK service for Welin Lambie Davit Flow Divider Install

1. Background and Current Observed Issues

CGC MOHAWK's dual point davit cables do not raise and lower at the same rate. The cutter requires a Welin Lambie Technician to install and calibrate a new flow divider.

Dual Point Davit System information: TW.PIV 5.0B Serial Number #5558/35A

2. REFERENCES

Technical Manual: Welin Lambie Dual Point Davit Model TW.PIV 5.0B Document number 3943-583-A

3. REQUIREMENTS

- 1- Technical Representative (Tech Rep) shall travel to CGC Mohawk in Key West, FL.
- 2- Tech Rep shall install Rotary Flow Divider, part number 894-01904.
- 3- Tech Rep shall calibrate/op test and ensure the davit is fully operational upon completion.

4. PERIOD OF PERFORMANCE

- a. FWD is in port and planning for tech services for the primary date.
 - i. Primary: May 19-May 21, 2025
 - ii. Secondary:

5. PLACE OF PERFORMANCE

The primary place of performance shall be at CGC MOHAWK located at below address:

CGC MOHAWK
100 Trumbo Road
Key West, FL 33040

Contracting Officer Technical Representative (COR):
Attention: LT. Michael Gandara, EO
Ship: 206-815-3497
Email: michael.j.gandara@uscg.mil