

Statement of Work (SOW)

For services to USCGC SENECA OILY WATER SEPARATOR SYSTEM

1. Background and Current Observed Issues

CGC SENECA is requesting a NEW OILY WATER SEPARATOR in the ENGINE ROOM. Current status of installed unit is not operable. Procured TECH services from SFLC by OEM manufactures has deemed installed unit would cost more to repair than to replace. The oily water separator allows SENECA to pump dirty oil and oily waste tanks while underway, allowing SENECA to empty bilges more regularly and better manage dirty oil and oily waste tank levels.

2. REFERENCES

MPC M-S-14135

CPL 766CYU50A1

TP 9149-593-A, Oily Water Separator (OWS) Model WSE-5-01-037

3. REQUIREMENTS

EO Vendor to provide NEW OWS system. Vendor will provide the unit to replace current. Operational test will be completed by SF w/ supervisor of GEA.

4. PERIOD OF PERFORMANCE

Conduct repairs/train personnel: 01 September

5. PLACE OF PERFORMANCE

The primary place of performance shall be at CGC SENECA located at below address:

CGC SENECA

4000 Coast Guard Blvd

Portsmouth, VA 23703

Contracting Officer Technical Representative (COR):

LT Cody Tecson, EO

Cell: (757) 613 0558

Email: cody.j.tecson@uscg.mil