

FLEX-500 electronic Governor
USCGC CYPRESS (WLB 210)

1. **Background.** CGC CYPRESS's prototyped FLEX-500 electronic Governor is malfunctioning causing an un-commanded De-clutch of the Master Engine. While shifting from maneuvering mode to transit mode at handle position zero, the Engine RPMs drop 5% below the Speed reference set point on the FLEX 500 causing the Master/primary Main Diesel Engine (MDE) to De-Clutch.
2. **Scope.** Request service technicians to come on sight to diagnose the issue causing the un-commanded De-Clutch and dial in both FLEX-500s. Ships forces will be on location to operate the machinery plant and conduct clutch in of both Main Diesel Engines (MDE). Techs will be available to plug into the FLEX-500 electronic Governor to conduct troubleshooting diagnostics and adjustments. This work will need to be conducted pier side, as CGC Cypress (WLB-210) cannot currently get underway.
3. **Objective.** The objective of this requirement is to troubleshoot, diagnose, calibrate and ultimately fix the Flex-500 preventing further un-commanded De-clutches of the MDEs. Ships forces will remain on scene with Tech technicians and conduct multiple propulsion plant evolutions until both technicians and CYPRESS Crew are both satisfied.
4. **Tasks.** The contractor shall provide one of each: laptop to plug into flex-500, and FLEX-500 tech pub.
5. **Delivery.** Contractor shall provide once available.
6. **Government furnished property.** N/A
7. **Security Requirement.** N/A
8. **Place of performance:**
CGC CYPRESS (WLB – 210) 15250
190651 CHINIAK HWY
KODIAK AK, 99615
9. **Period of performance-** 15Apr25 – 01Jun25
10. **Points of Contact.**
10.1. USCGC CYPRESS: CWO2 Edward A. Cordova, email: edward.a.cordova@uscg.mil Phone: 530-933-8984
10.2. USCG-SFLC-IBCTPL Asset Management: EMCS Daniell Hurtado. daniell.e.hurtado@uscg.mil 510-290-8808