

August 23, 2021

R. Brett Barry, P.E.
Supervisory Civil Engineer
Forest Service
Boise National Forest
1249 S. Vinnell Way, Suite 200
Boise, ID 83709

Re: Gloria Ford Property Hazardous Materials Report, Contract Number 1240LR21P0058

Dear Mr. Barry:

Water, Civil, and Environmental Inc. (WCE Inc.) has conducted a hazardous materials survey to identify potentially hazardous materials associated with the Gloria Ford Property, located in Township 8N, Range 5E Section 2, Lots 9, 12, and 13 and Section 11, Lots 3 and 6 (herein referred to as the "Property"). The Property is accessible from State Highway 17 (Banks-Lowman Road). During the site inspections, which were conducted on July 19, 2021, and August 18, 2021, WCE Inc. personnel examined the Property for universal wastes, hazardous materials/wastes, and toxic wastes, including the following:

- Mercury (Hg) thermostats.
- Hg fluorescent lights.
- PCB ballasts or transformers.
- Refrigeration or A/C units containing CFCs.
- Smoke detectors.
- Propane containers.
- Containers of liquids or hazardous waste.
- Vehicle batteries.

A list of the quantity and location of each material/waste that will require removal/disposal or recycling before demolition is included in Table 1. Photographs of the materials are found in Appendix 1.

LIMITING FACTORS

This report is based upon the condition of the Property, accessibility of the structures present on the Property, and materials observed at the time of the site inspections. No samples were collected as part of the investigation. In 1996, landslide flow intruded the Property, covering much of the area around the structures and partially filling the main house with sand and rocks. Notably, the debris partially buried two 55-gallon drums in Shed 3, preventing WCE Inc. personnel from determining whether they contained hazardous materials. It should be noted that the landslide flow also may have completely buried additional debris and containers of hazardous materials so that they could not be observed from the surface. In addition to the limitations due to the landslide, several containers observed in the main house contained liquids but were unlabeled. A summary of the hazardous materials and unlabeled containers is included in Table 1.

Appendix D.

Table 1. Location and Amount of Hazardous Materials Observed on the Property.

Building	Location	Accessibility	Hazardous Material	DOT Hazard Class	Estimated Quantity
Main House	South side, exterior	Accessible	Fuel in above-ground storage tank	3, flammable	1, 300-gallon tank, partially full
	Storage room on southeastern side	Largely covered by landslide flow	All-purpose alkyd enamel	3, flammable	3, 1-quart containers, full
			Flat enamel paint	3, flammable	1, 1-gallon container, 1/3 full
			Waterproof cement	3, flammable	1, 1-quart container, 1/3 full
			Semi-transparent oil stain	3, flammable	1, 1-gallon container, 1/3 full
			Interior enamel paint	No DOT hazard class, but environmentally hazardous	1, 1-quart container, 1/2 full
			Caulking compound	3, flammable	1, 11-ounce container, full
			Wood finish	3, flammable	1, 1-quart container, less than 1/4 full
			Drain cleaner	8, corrosive material	1, 1-pint container, 1/4 full
			Patio furniture stain	3, flammable	1, 1-quart container, 3/4 full
			Latex semi-gloss enamel paint	No DOT hazard class, but environmentally hazardous	1, 1-quart container, 1/4 full
			Snail, slug, and insect killer bait	No DOT hazard class, but toxic to wildlife	1, 14-ounce box, less than 1/4 full
			Unknown	Unknown	4, 15-fl oz rusted cans, full 1, 1-gallon unlabeled plastic bleach bottle, full
	Kitchen/dining area	Landslide flow intrusion in dining room area	Unknown	Unknown	1, 5-gallon clear plastic container, 1/4 full 1, 1-pint white plastic juice jug, full
			Deep gloss floor finish	No DOT hazard class, but environmentally hazardous	1, 1-gallon, less than 1/4 full

Appendix D.

Table 1. Location and Amount of Hazardous Materials Observed on the Property, continued.

Building	Location	Accessibility	Hazardous Material	DOT Hazard Class	Estimated Quantity
Main House	Living room/ bathroom area	Landslide flow intrusion	409 spray cleaner	No DOT hazard class, but environmentally hazardous	1, 12-ounce spray can, 1/5 full
			Pine-Sol spray cleaner and disinfectant	Not hazardous	1, 12-ounce spray bottle, 1/2 full
	Exterior, north side	Accessible	K-57 septic tank & cesspool cleaner	Not hazardous	1, 1-pint bottle, 3/4 full
Shed 3	Interior	Building is collapsed, partially buried by landslide flow	Unknown	Unknown	3, 55-gallon steel drums: one partially full, two appearing to be partially full
Shed 4	Interior	Accessible	Unknown	Unknown	1, 1-gallon plastic container, 1/3 full
	Exterior, south side	Accessible	Chevron Duraplex Grease	No DOT hazard class, but level 3 acute toxicity for aquatic environments	1, 5-gallon bucket, partially full

CONCLUSION

WCE Inc. has performed a hazardous materials inspection of the Gloria Ford Property, located along Highway 17 in Boise County, Idaho. WCE Inc. recommends that the hazardous materials observed be removed and disposed of properly before demolition of the structures on the Property. Additionally, the partially buried 55-gallon drums should be unearthed and any unidentified substances in them and in the other unlabeled containers observed should be characterized and properly disposed of.

Appendix D.

APPENDIX 1

Hazardous Materials Photographs

Appendix D.



Figure 1: Exterior of main house, facing northwest, above-ground heating oil tank in foreground.



Figure 2: Pint of K-57 septic tank and cesspool cleaner outside of main house, full.



Figure 3: Kitchen in main house, deep gloss floor cleaner, less than 1/4 full.



Figure 4: Pint plastic juice jug in kitchen of main house, full.



Figure 5: 12-oz. can of 409 spray cleaner in bathroom of main house, 1/5 full.



Figure 6: Drain cleaner, 1/4 full.

Appendix D.



Figure 7: Quart containers of all-purpose alkyd enamel, full.



Figure 8: 11-oz. container caulking compound, full.



Figure 9: One-gallon container of interior enamel paint, $\frac{1}{2}$ full.



Figure 10: 14-oz box slug, slug, and insect killer, less than $\frac{1}{4}$ full.



Figure 11: Quart of patio furniture stain, $\frac{3}{4}$ full.



Figure 12: Semi-transparent oil stain, $\frac{1}{3}$ full.

Appendix D.



Figure 13: Quart of waterproof cement, $\frac{1}{3}$ full.



Figure 14: Quart of wood finish, less than $\frac{1}{4}$ full.



Figure 15: 55-gallon steel drums inside Shed 3.



Figure 16: 5-gallon container of grease in front of Shed 4, partially full.



Figure 17: Soil staining and spillage of grease.



Figure 18: Unlabeled one-gallon plastic container inside Shed 4, $\frac{1}{3}$ full