

(TARS Class)

0400

ITEM NO. 0401

UHF SATCOM SERVICE

CATEGORY "A"

CONTRACT NO.

TBD

Period of Performance (16 May – 17 May 2026)

Location XXXXXXXXXX

1.0 ABSTRACT: Hire the service of USA Technical Representative to Troubleshoot, Repair, and Test the UHF SATCOM System.

2.0 REFERENCES/ENCLOSURES:

- 2.1 TD-1271B/U Multiplexer Technical and Operation Manual. (available onboard)
- 2.2 OK-454(V)/WSC Control-Monitor Group technical Manual. (available onboard)
- 2.3 ANTENNA GROUP OE-82C/WSC-1(V) Operation and Maintenance Instructions. (available onboard)
- 2.4 Satellite Communications Sets AN/WSC-3(V) Operation and Maintenance Instructions. (available onboard)
- 2.5 C-10315/U Operation, Maintenance, and Installation Technical Manual. (available onboard)

3.0 ITEM LOCATION/DESCRIPTION:

AN/WSC-3	UHF SATCOM TRANSCIEVER Qty 2	01-49-2-C
TD-1271B/U	MULTIPLEXER Qty 1	01-49-2-C
OK-454 (V) /WSC	CONTROL-MONITOR GROUP	01-49-2-C
OE-82C/WSC-1	UHF SATCOM ANTENNA GROUP Qty 1	01-49-2-C
C-10315/U	REMOTE SWITCHING CONTROL	01-49-2-C

4.0 GOVERNMENT FURNISHED EQUIPMENT/MATERIAL/SERVICES: NONE

5.0 NOTES:

5.1 Known issues:

- 5.1.1 WSC-3 #1 and #2 will not key locally or remotely.
- 5.1.2 Not able to key radios from C-10315 through OK-545/TD-1271. TD-1271 recently replaced by ships force.

6.0 QUALITY ASSURANCE REQUIREMENTS: None additional

7.0 STATEMENT OF WORK REQUIRED:

0400

ITEM NO. 0401

UHF SATCOM SERVICE

CATEGORY "A"

CONTRACT NO.

TBD

- 7.1 Provide the services of a qualified technician intimately familiar with the ARS Class UHF SATCOM Systems to Test, Troubleshoot, Perform Repairs, Align, Operate, and Train onboard operators. Equipment alignments shall be conducted in accordance with equipment technical manuals ref. 2.1 through 2.5. Contractor shall notify the MSC REP and ships force "CRET" of any major subassemblies, circuit board, or modules requiring replacement to allow the Ships force to procure same to effect equipment repairs.
- 7.2 Provide a detailed written report to the MSC REP stating the condition of each piece of equipment.
- 7.3 Tech Rep shall provide daily briefings to the MSC REP and upon completion of work submit a detailed written report of all work performed, work outstanding, and recommendations for follow-up to ensure a fully functional communication system.
- 7.4 Tech Rep shall upon completion of Testing, Repairs, and Alignments conduct Full Operational Testing of a circuit off ship to validate both Transmit and Receive functionality of the system.
- 7.5 Tech Rep shall conduct 4 hours of Training with the ships communication system personnel for the UHF SATCOM system operations, configuration, and basic troubleshooting.

8.0 GENERAL REQUIREMENTS:

- 8.1 The contractor shall assist the USA Technical Representative with visa requirements to enter the country if assistance is required.