

Site Inspection Report

Inspector: Eng. Rania Al-Rashid | Date: 05 June 2025 | Reference: INS-2025-0412

1. Inspection Scope

Routine condition assessment of five (5) Seha portfolio assets in Abu Dhabi. Sites visited in sequence over two days. GPS coordinates recorded at each site entrance and key boundary points using Garmin GPSMAP 66sr.

Site	Address	GPS (Entry)	Condition	Action Required
Seha Main	Al Salam St, Mussafah	24.4653°N, 54.3718°E	Good	None
Seha Clinic Al Rahba	Al Rahba District, MBZ City	24.3214°N, 54.5432°E	Fair	Paint exterior
Seha Pharmacy Hub	Al Nahyan Camp, Abu Dhabi	24.4012°N, 54.3876°E	Good	HVAC service due
Seha Emergency Annex	Khalidiyah, Abu Dhabi City	24.4789°N, 54.3456°E	Poor	Roof repair urgent
Seha Admin Support	Mussafah M-44 Industrial	24.4512°N, 54.3921°E	Good	Security upgrade

2. Critical Finding — Seha Emergency Annex

Location: Khalidiyah District, Abu Dhabi | GPS: 24.4789°N, 54.3456°E

Roof membrane failure identified on the east wing. Affected area approximately 320 sqm. Water ingress visible in consultation Room C. Immediate remediation required before onset of summer humidity season. Estimated remediation cost: AED 180,000.

3. Boundary Coordinate Records

Asset	Boundary Point	Latitude	Longitude	Marker Type
Seha Main	Gate Post North	24.465312	54.371840	Metal post
Seha Main	Gate Post South	24.464100	54.371820	Metal post
Seha Clinic	NW Corner	24.322100	54.542400	Concrete pillar
Seha Clinic	SE Corner	24.320800	54.544100	Concrete pillar
Seha Annex	Entrance	24.478900	54.345600	Gate frame
Seha Admin	Main Boundary	24.451200	54.392100	Chain link fence