Proprietary to General Electric Company
Direction 5438996-8EN, **Rev#** 9
Brivo CT385 Series Service Methods (Adv)
Module Version 1.0, **Version Date** 1/14/13

Collimator Calibration

(Click Here for Summary Version)

1 Personnel Requirements

Required Persons	Preliminary Reqs	Procedure	Finalization
1	N/A	15 mins	N/A

2 Overview

This document provides necessary steps to detailed calibrate the system.

Last Revised:	17 May, 2012

3 Preliminary Requirements

3.1 Safety



⚠ CAUTION
Remove any objects from scan window area which may interfere with the rotating gantry.



⚠ CAUTION
No personnel or patients should be in the area of the gantry while scanning without adequate radiation safety precautions being utilized.

3.2 Required Conditions

Condition	Reference	Effectivity
Recommend procedure completion by GE Service trained personnel.	-	-
Gantry covers and scan window installed.	-	-

4 Procedure

1. Move table to longitudinal home position.
2. Click [Calibration].
3. Click [COLLIMATOR CALIBRATION].
4. Click [OK] in *Attention* window.
5. Press [START] on GSCB when it flashes.
6. Click [OK] in *Attention* window.
7. Click [QUIT] in *Scanner Utilities* window.

5 Finalization

1. *Detailed Calibration*
2. *Fast Calibration*

3. Save System State

Back to top