

1) I/O Connection



2) Pulse Out


Pulse Output Module
Stepping Motor Driver
Distributed pulse output
Photocoupler
+5V
CCW1
3
CCW
CW1
5
CW
C-OFF1
7
Output power supply OFF
B-FREE1
9
Magnetic brake release
0V(5V)
OVER
11
Overheat input
TIMING
13
Magnetic excitation timing input
External power supply 0V (+5V)
15
External power supply +5V
14
0V (5V)
5 VDC external power supply