ECE 401 Octo 2 Soldering 1. turn on soldering station 2. While from heals up, set up helping hands

3. Arrange components on table 4. make sure iron is plugged in 5. resistors (3 in middle) 6. Electrolytic capacitors(3) 7. Ship long leads 8. 8-pinconnecter 9, LED 10. Disc capacitors 3) 11. Snip leads again 12,0:0de 13. 12-pin Connector 14. remaining resistors (2) 15, trasistors (2) I Esnip leads 17, get new pcb and solder 18, Asan capacitor 19 a transistor (NPN) 20. LED

21, Ship leads 22, 2,2MS2 sesistor 23, fantalum capacitor 24, speaker 25. 0iodes(2) 26, sesistos(2) 27, sn; plads 28, transistor (PNP) 29. Poverlines 30, year (4 leads 31, test with battery 32 clean up