735. No individual grease traps hall be installed for a facility that has an approved rate of flow of more than \_\_\_\_\_ nor less than

(a) 1.3 L/s, 3.4 L/s

(b) 0.75 L/s, 1.2 L/s

- (c) 1.5 L/s, 2.3 L/s
- (d) 2.3 L/s, 3.4 L/s

736. Which type of fire line installation has become obsolete and seldom installed?

(a) Automatic system

(c) Local vent

(b) Wet standpipe

(d) Dry standpipe