- 553. What should be done whenever a partition contains some piping and runs parallel to the floor joist underneath?
 - (a) Notching should be introduced into the joist
 - (b) Adjust the joist to make it perpendicular with the direction of pipe
 - (c) Space the joist wider to accommodate the pipe
 - (d) Double the joist

554. Thread on plastic pipe shall be factory cut or molded. Threaded plastic pipe shall be schedule _____ wall thickness.

(a) 40

(c) 120

(b) 80

(d) 60