C Axis Disable Procedure

- # Insert Pendrive
- # Press Yes
- # Press Backup (Config, Alarm, Program).
- # Program & Service
- # PW = 159357
- # Program & Service
- # Settings
- # Select C Axis
- # Select Option Code
- # Enter 12723243
- # Press ESC button
- # Press Save
- # After Configuration saved Restart the Robot.