Connection of RS-485 interface uses a two-wire line.



Figure 12 - Modbus RTU Wiring Schematic

Install a 120 Ohm termination resistor at the end of the line.