


Independent enable protection | DRAFT | all rails and fault detectors must be completed


Watchdog pulses must follow validated sequential current updates. GPIO38 ARM_REQUEST requires explicit re-arm after any fault.

Timer and logic bounds are modeled; DRV8962 EN delay uses its specified maximum. No arbitrary overcurrent protection is claimed.

















































































Sheet: /		
File: protection.kicad_sch		
Title: Independent current-control enable protection – DRAFT		
Size: A3	Date:	**Rev: working**
KiCad E.D.A. 9.0.8		Id: 1/1