## Clover 3 MP Release 3 -18 Nov

## Change Log:

- Fixed Silence issue.
- Disabled debug log on com.

Model	Clover C3 - AC - 1042135
Firmware Bundle Version	3.01.111.1307.103.01_(AC)_Clover_US
Link in Engineering drive where firmware is located	Uploaded to this page  O:\Engineering\C3_SOFTWARE_RELEASE\AC10-500V2_AWS_3.01.111.1307.103.01_(AC)_Clover_US.zip
App version to perform pairing test	iOS: 1.79.0.10 Android: 1.1.1.119
Comm firmware version	1307.103.01
PIC firmware version	111 (SW1-0235-000B_AC10-500_111_USA.X.production.hex - Checksum = 0x482E)
Environment to serialize	prod
Md5Sum	serial_mwm.bin: 0bd3d591eae47698c7027b9fe863c9fa

Model	Clover C3 - DC - 1042136
Firmware version	3.01.508.2307.203.01_(DC)_Clover_US
Link in Engineering drive where the firmware is located	Uploaded to this page  O:\Engineering\C3_SOFTWARE_RELEASE\DC10-500V2_AWS_3.01.508.2307.203.01_(DC)_Clover_US.zip
App version to perform pairing test	iOS: 1.79.0.10 Android: 1.1.1.119
Comm firmware version	2307.203.01
PIC firmware version	508 (SW1-0234-000B_DC10-500_508_USA.X.production.hex - Checksum = 0x653C)
Environment to serialize	prod
Md5Sum	serial_mwm.bin : 80602bdfcb9cae7039550e247b4b07b6