

ACN: 2372077

Time / Day

Date : 202606

Local Time Of Day : 1201-1800

Place

Locale Reference.ATC Facility : F11.TRACON

State Reference : FL

Altitude.MSL.Single Value : 2100

Aircraft : 1

Reference : X

ATC / Advisory.TRACON : F11

Make Model Name : Small Aircraft, Low Wing, 2 Eng, Retractable Gear

Operating Under FAR Part : Part 91

Flight Plan : IFR

Flight Phase : Initial Climb

Airspace.Class C : SFB

Aircraft : 2

Reference : Y

ATC / Advisory.TRACON : F11

Make Model Name : Small Transport, Low Wing, 2 Turboprop Eng

Flight Plan : IFR

Flight Phase : Initial Climb

Airspace.Class D : ORL

Person

Location Of Person.Facility : F11.TRACON

Reporter Organization : Government

Function.Air Traffic Control : Approach

Qualification.Air Traffic Control : Fully Certified

Experience.Air Traffic Control.Time Certified In Pos 1 (yrs) : 16

ASRS Report Number.Accession Number : 2372077

Human Factors : Communication Breakdown

Communication Breakdown.Party1 : ATC

Communication Breakdown.Party2 : Flight Crew

Events

Anomaly.ATC Issue : All Types

Anomaly.Conflict : Airborne Conflict

Anomaly.Deviation / Discrepancy - Procedural : Published Material / Policy

Anomaly.Ground Event / Encounter : Ground Equipment Issue

Detector.Person : Air Traffic Control

Result.Flight Crew : Requested ATC Assistance / Clarification

Result.Air Traffic Control : Separated Traffic

Assessments

Contributing Factors / Situations : ATC Equipment / Nav Facility / Buildings

Contributing Factors / Situations : Human Factors

Primary Problem : ATC Equipment / Nav Facility / Buildings

Narrative: 1

I was released Aircraft Y off Runway 7 while also tagging up inbounds for SFB and receiving constant VFR departures. I noticed we were only getting partial readbacks and no readbacks from other aircraft. We switched to Standby Transmitter, then approximately 30 minutes after, we completely lost the frequency on both Mains and Standbys. Both aircraft were separated by 8.64 miles. We jumped to the Emergency Backup Orange Jack, still with no response. Later on after the situation we found that Aircraft Y was trying to get us and eventually jumped to Sector Y.

Synopsis

F11 TRACON Controller reported losing the main and standby transmitter frequencies while working a busy satellite airport departure sequence, with a resulting loss of communication with departing aircraft.