

ACN: 2373712
Time / Day
Date : 202606
Local Time Of Day : 1801-2400
Place
Locale Reference.Airport : DCA.Airport
State Reference : DC
Altitude.AGL.Single Value : 0
Aircraft
Reference : X
ATC / Advisory.Ground : DCA
Aircraft Operator : Air Carrier
Make Model Name : Commercial Fixed Wing
Crew Size.Number Of Crew : 2
Operating Under FAR Part : Part 121
Flight Plan : IFR
Mission : Passenger
Flight Phase : Taxi
Person : 1
Location Of Person.Aircraft : X
Location In Aircraft : Flight Deck
Reporter Organization : Air Carrier
Function.Flight Crew : Check Pilot
Function.Flight Crew : Pilot Flying
Function.Flight Crew : Captain
Qualification.Flight Crew : Multiengine
Qualification.Flight Crew : Instrument
Qualification.Flight Crew : Air Transport Pilot (ATP)
ASRS Report Number.Accession Number : 2373712
Human Factors : Confusion
Human Factors : Communication Breakdown
Human Factors : Situational Awareness
Communication Breakdown.Party1 : Flight Crew
Communication Breakdown.Party2 : ATC
Person : 2
Location Of Person.Aircraft : X
Location In Aircraft : Flight Deck
Reporter Organization : Air Carrier
Function.Flight Crew : First Officer
Function.Flight Crew : Pilot Not Flying
Qualification.Flight Crew : Multiengine
Qualification.Flight Crew : Instrument
Qualification.Flight Crew : Air Transport Pilot (ATP)
ASRS Report Number.Accession Number : 2373718
Human Factors : Situational Awareness
Human Factors : Confusion
Human Factors : Communication Breakdown
Communication Breakdown.Party1 : Flight Crew
Communication Breakdown.Party2 : ATC
Events
Anomaly.Deviation / Discrepancy - Procedural : Clearance
Anomaly.Ground Incursion : Taxiway
Detector.Person : Flight Crew
When Detected : Taxi
Result.Flight Crew : Became Reoriented
Result.Air Traffic Control : Issued New Clearance
Assessments
Contributing Factors / Situations : Airport

Contributing Factors / Situations : Chart Or Publication

Contributing Factors / Situations : Human Factors

Contributing Factors / Situations : Procedure

Primary Problem : Airport

Narrative: 1

Was told to enter runway 15 at the departure end and taxi down on the runway and exit on K into the holding bay of 19. When taxiing down while referencing the airport chart/amm (Airport Moving Map) it looked as if it was the second exit to the left. We passed S, and didn't see any signage for K on the eastern side of the runway and accidentally taxied past. Ground told us to simply stop and take the next left on Juliet.

Narrative: 2

We were in the holding bay for 15 to burn off fuel since we were overfueled at the gate at DCA. We were told to taxi to runway 19 via runway 15, left on kilo. As we were taxiing down 15 there were no signs indicating a left turn off for taxiway kilo. The taxi chart is misleading because it shows a gap in the pavement between kilo and sierra indicating kilo should be the second left turn off of runway 15. Before I could speak up ground told us to stop and informed us we missed kilo and to take the next left onto Juliet.

Synopsis

Air carrier flight crew reported that they missed the turn onto Taxiway K from Runway 15 at DCA due to insufficient taxiway signage and confusing chart depiction.