

ACN: 2373953

Time / Day

Date : 202606

Local Time Of Day : 0601-1200

Place

Locale Reference.Airport : ORD.Airport

State Reference : IL

Altitude.MSL.Single Value : 4000

Environment

Flight Conditions : VMC

Aircraft

Reference : X

ATC / Advisory.Tower : ORD

Aircraft Operator : Air Carrier

Make Model Name : Commercial Fixed Wing

Crew Size.Number Of Crew : 2

Operating Under FAR Part : Part 121

Flight Plan : IFR

Mission : Passenger

Flight Phase : Final Approach

Airspace.Class B : ORD

Person

Location Of Person.Aircraft : X

Location In Aircraft : Flight Deck

Reporter Organization : Air Carrier

Function.Flight Crew : Pilot Flying

Function.Flight Crew : First Officer

Qualification.Flight Crew : Air Transport Pilot (ATP)

Qualification.Flight Crew : Multiengine

Qualification.Flight Crew : Instrument

ASRS Report Number.Accession Number : 2373953

Human Factors : Workload

Events

Anomaly.ATC Issue : All Types

Anomaly.Deviation - Track / Heading : All Types

Anomaly.Deviation / Discrepancy - Procedural : Published Material / Policy

Anomaly.Ground Event / Encounter : Ground Equipment Issue

Detector.Person : Flight Crew

When Detected : In-flight

Result.Flight Crew : Became Reoriented

Result.Flight Crew : Overcame Equipment Problem

Result.Flight Crew : Requested ATC Assistance / Clarification

Assessments

Contributing Factors / Situations : ATC Equipment / Nav Facility / Buildings

Primary Problem : ATC Equipment / Nav Facility / Buildings

Narrative: 1

Flying into ORD on 27R we were cleared the visual 27R. We had it backed up with the ILS which had no NOTAMs. The airplane in front of us asked if there were any issues with the ILS and tower responded that there should be none. As we captured the localizer the plane started to turn but went through the approach by about half a dot on the localizer. We realized the localizer had us lined up next to the course so we turned off the autopilot and continued for a visual approach with out issue. We reported this issue to the tower.

Synopsis

Air carrier First Officer reported ORD Runway 27R ILS localizer was not properly calibrated.