

ACN: 2374147
Time / Day
Date : 202606
Local Time Of Day : 1201-1800
Place
Locale Reference.Airport : TBPB.Airport
State Reference : FO
Aircraft
Reference : X
Aircraft Operator : Air Carrier
Make Model Name : Large Transport, Low Wing, 2 Turbojet Eng
Crew Size.Number Of Crew : 2
Operating Under FAR Part : Part 121
Flight Plan : IFR
Mission : Passenger
Flight Phase : Parked
Component
Aircraft Component : Electronic Library (other than Nav database)
Aircraft Reference : X
Problem : Malfunctioning
Person
Location Of Person.Aircraft : X
Location In Aircraft : Flight Deck
Reporter Organization : Air Carrier
Function.Flight Crew : Captain
Qualification.Flight Crew : Air Transport Pilot (ATP)
Qualification.Flight Crew : Multiengine
Qualification.Flight Crew : Instrument
ASRS Report Number.Accession Number : 2374147
Human Factors : Confusion
Human Factors : Communication Breakdown
Communication Breakdown.Party1 : Flight Crew
Communication Breakdown.Party2 : ATC
Events
Anomaly.Aircraft Equipment Problem : Less Severe
Anomaly.ATC Issue : All Types
Anomaly.Deviation - Track / Heading : All Types
Anomaly.Deviation / Discrepancy - Procedural : Clearance
Anomaly.Deviation / Discrepancy - Procedural : Published Material / Policy
Detector.Person : Flight Crew
When Detected : Pre-flight
Result.General : None Reported / Taken
Assessments
Contributing Factors / Situations : Chart Or Publication
Contributing Factors / Situations : Procedure
Primary Problem : Chart Or Publication
Narrative: 1

During preflight prep, ATIS was advertising noise abatement procedures for departures. Both the FO and I checked the Jepps 10-9, as well as the airport company pages departures notes for noise abatement procedures and found none. We both failed to reference the Jepps 10-4 page. Our ATC clearance was "Make a left turn to join Aircraft Y, climb to Level 300, and Squawk XXXX". When we were cleared for takeoff, there was no mention of the noise abatement procedure. In hindsight, I feel like previous departures the controller has issued the clearance of "Fly runway heading until 2,500 ft and then left turn on course, you are cleared for Takeoff". This tower controller simply gave us "Cleared for Takeoff" with no further instructions. We began our left turn on course after passing 400' AGL. During the turn, the tower controller reminded us in the future to fly the published noise abatement procedure. This was ultimately our mistake, but I feel misled by the way the airport company pages and the Jepps are constructed for BGI (TBPB).

Synopsis

Air carrier Captain reported confusing noise abatement procedure charting at BGI/TBPB.