

ACN: 2374348

Time / Day

Date : 202606

Local Time Of Day : 0601-1200

Place

Locale Reference.ATC Facility : LFRR.ARTCC

State Reference : FO

Altitude.MSL.Single Value : 32000

Environment

Flight Conditions : VMC

Aircraft : 1

Reference : X

ATC / Advisory.Center : LFRR

Aircraft Operator : Air Carrier

Make Model Name : B767 Undifferentiated or Other Model

Crew Size.Number Of Crew : 3

Operating Under FAR Part : Part 121

Flight Plan : IFR

Mission : Passenger

Flight Phase : Cruise

Aircraft : 2

Reference : Y

ATC / Advisory.Center : LFRR

Aircraft Operator : Air Carrier

Make Model Name : A330

Flight Plan : IFR

Flight Phase : Cruise

Person

Location Of Person.Aircraft : X

Location In Aircraft : Flight Deck

Reporter Organization : Air Carrier

Function.Flight Crew : Pilot Not Flying

Function.Flight Crew : First Officer

Qualification.Flight Crew : Air Transport Pilot (ATP)

Qualification.Flight Crew : Instrument

Qualification.Flight Crew : Multiengine

ASRS Report Number.Accession Number : 2374348

Analyst Callback : Attempted

Events

Anomaly.Inflight Event / Encounter : Wake Vortex Encounter

Anomaly.Inflight Event / Encounter : Loss Of Aircraft Control

Detector.Person : Flight Crew

When Detected : In-flight

Result.Flight Crew : Regained Aircraft Control

Result.Flight Crew : Requested ATC Assistance / Clarification

Assessments

Contributing Factors / Situations : Environment - Non Weather Related

Contributing Factors / Situations : Procedure

Primary Problem : Ambiguous

Narrative: 1

At cruise altitude of 320. An A330 was climbing ahead of us and we entered wake. We turned on seat belt sign as we felt turbulence. This wake turbulence event caused an upset. Aircraft rolled 30-40 degrees bank and nose down pitch of about 5 degrees. We initiated an upset recovery. Called Upset, disconnected autopilot and auto thrust. Push, roll, thrust, stabilize calls were made as the occurrence was very quick and righted quickly. Stabilized aircraft. Notified ATC. ATC told us the aircraft was an A330. Checked in with the Flight Attendants, no injuries had occurred. Maintained seat belt sign for an extended time.

Synopsis

B767 First Officer reported an inflight upset occurred when they encountered wake turbulence at FL320 in

trail of an A330. Control was regained and the flight continued to its destination.