

## EMERGENCY LIGHTING PERIODIC INSPECTION REPORT

Issued with Monolith Beacon · visit record for an existing installation  
BS 5266-1:2016 · BS EN 50172 / BS 5266-8

Beacon report

Page 1

Ref: SAMPLE-PIR-20260714

Acme Lighting Ltd

### A Client details

Client  
Riverside Court Management

Address  
12 Quay Road, Bristol

### B Installation and system

Installation / premises  
Riverside Court

Installation address  
12 Quay Road, Bristol

Responsible person  
Jordan Site Manager

Date system commissioned  
Unknown

System duration  
3 hours

Automatic test system fitted  
No

### Operating mode

Mode  
Non-maintained

### C Overall assessment

**UNSATISFACTORY**

Next inspection due  
14 Jul 2027

This visit  
Annual 3 hours · 3 tested · 1 failed

### D Inspecting organisation

Trading title  
Acme Lighting Ltd

Address  
14 Quay Street, Bristol, BS1 4QH

Contact  
0117 000 0000 · www.example.co.uk

### COMPETENT PERSON

J. Hart · Competent person · 14 Jul 2026



## EMERGENCY LIGHTING PERIODIC INSPECTION REPORT

Issued with Monolith Beacon · visit record for an existing installation  
BS 5266-1:2016 · BS EN 50172 / BS 5266-8

Beacon report

Page 2

Ref: SAMPLE-PIR-20260714

Acme Lighting Ltd

### E Changes since last inspection

Notes

No modifications to the installation reported.

### F Tests carried out on this visit

| Date        | Test type      | Result | Engineer | Notes            |
|-------------|----------------|--------|----------|------------------|
| 14 Jul 2026 | Annual 3 hours | FAIL   | J. Hart  | 1 fitting failed |

#### After a duration test

A full duration test runs the batteries down. Until they recharge, the emergency lighting may not cover another power cut. Plan these tests for quieter times, or test alternate fittings.

### G Findings and actions

#### Finding 1

|                                                           |                       |
|-----------------------------------------------------------|-----------------------|
| Luminaire reference<br>EL-02                              | Failed<br>14 Jul 2026 |
| Location<br>Stair core · Ground · Stair B                 |                       |
| Details<br>Lamp did not strike on test                    |                       |
| Interim measures<br>Temporary torch station placed nearby |                       |
| Repair<br>Replace lamp / gear tray on next attendance     |                       |

#### Notes for the recipient

Keep this report with your emergency lighting records and logbook.

This report was prepared with Monolith Beacon. It records the outcome of a visit to inspect and test the emergency lighting at this site, in line with BS 5266-1:2016 and BS EN 50172.

If something failed: arrange repair with a competent person, check who is at higher risk until it is fixed, and put temporary measures in place if needed (for example temporary torches, extra checks, or limiting use of the area).

It is not a certificate for new installation work, and it is not a substitute for a formal periodic inspection certificate if your organisation or insurer asks for one.

Give this report to the Responsible Person for the premises. If how the building is used changes, arrange a new fire risk assessment.