SensorManager::calibrate SCD30 Sensor Manager:: check And CalibrateSCD30 DisplayManager::initialize SensorManager::initialize Sensors Logger::info loop DisplayManager::runDisplay Check I2CScanner::scan setup