

TITAN 500 INDUSTRIAL PUMP MANUAL

Model: Titan-500-X1

Manufacturer: EnviroJim Systems

PARTS LIST

- Item: Hydraulic Seal, P/N: HS-99, Criticality: High.
- Item: Pressure Valve, P/N: PV-22, Criticality: Medium.

MAINTENANCE PROCEDURES

Procedure: Quarterly Inspection

1. Verify oil levels in the main reservoir.
2. Check for leaks around the HS-99 seal.
3. Calibrate the PV-22 valve.

FAULT DETECTION

Fault: Low Discharge Pressure

Symptoms: Reduced flow rate, erratic gauge readings.

Root Cause: Worn hydraulic seal (HS-99).

Correction: Replace seal and reset the unit.