

BMS Flash Fault

Alarm Attribute

Alarm name	Alarm Severity	Alarm Category
BMS Flash Fault	General	Battery alarm

Possible Cause

Cause ID	Possible Cause
1	BMS Flash Fault.

Suggestion

1. Upgrade the firmware to the latest version and restart the battery.
- 2.If the issue remains, provide the completed troubleshooting results to SolaX technical support team through video or images.Including but not limited to:
 - 1) SN number of the inverter.