

BMS Manufacturer Mismatch

Alarm Attribute

Alarm name	Alarm Severity	Alarm Category
BMS Manufacturer Mismatch	General	Battery alarm

Possible Cause

Cause ID	Possible Cause
1	BMS Manufacturer Mismatch.

Suggestion

1. Upgrade both the BMS and the battery to the latest firmware. If the error persists, provide the battery SN to SolaX technical support team for analysis.