

BMS Master&Slave Software Mismatch

Alarm Attribute

Alarm name	Alarm Severity	Alarm Category
BMS Master&Slave Software Mismatch	General	Battery alarm

Possible Cause

Cause ID	Possible Cause
1	The master battery software and hardware do not match.

Suggestion

1. Upgrade the battery firmware to the latest version.
2. If the problem remains, provide the inverter's SN number to the SolaX technical support team for further analysis.