

BMS Temperature Difference Fault

Alarm Attribute

Alarm name	Alarm Severity	Alarm Category
BMS Temperature Difference Fault	General	Battery alarm

Possible Cause

Cause ID	Possible Cause
1	BMS Temperature Difference Fault.
2	The difference between the maximum and minimum battery temperature probes is higher than normal.

Suggestion

1. Upgrade the battery firmware to the latest version.
2. Use the T-BAT-Charger to check the detailed cell temperature information of each battery, and provide to the SolaX technical support team for further analysis.If the T-BAT-Charger is unavailable,provide the inverter's SN number to the SolaX technical support team for further analysis.