

BMS Temperature Sensor Fault

Alarm Attribute

Alarm name	Alarm Severity	Alarm Category
BMS Temperature Sensor Fault	General	Battery alarm

Possible Cause

Cause ID	Possible Cause
1	Battery temperature sensor failure.

Suggestion

1. Update the BMS firmware.

Use the T-BAT-Charger to check the detailed cell temperature information of each battery, and provide to the SolaX technical support team for further analysis.If the T-BAT-Charger is unavailable,provide the inverter's SN number to the SolaX technical support team for further analysis.