

BMS Type Mismatch

Alarm Attribute

Alarm name	Alarm Severity	Alarm Category
BMS Type Mismatch	General	Battery alarm

Possible Cause

Cause ID	Possible Cause
1	Battery type mismatch fault.
2	The master battery and the slave batteries are not the same model.

Suggestion

1. Check whether the master's and slave batteries' model match, and upgrade the battery firmware to the latest version.
2. If the issue remains, provide the completed troubleshooting results to SolaX technical support team through video or images. Including but not limited to:
 - 1) SN number of the inverter.