

BMS Version Mismatch

Alarm Attribute

Alarm name	Alarm Severity	Alarm Category
BMS Version Mismatch	General	Battery alarm

Possible Cause

Cause ID	Possible Cause
1	Battery version mismatch.
2	The master battery's and the slave batteries firmware version are not compatible.

Suggestion

1. Upgrade the battery firmware to the latest version.
- 2.If the issue remains,provide the inverter's SN number to the SolaX technical support team for further analysis.